

Release Notes for Cisco 4000 Series ISRs, Cisco IOS XE Fuji 16.9.x

First Published: 2018-07-19

Last Modified: 2018-07-19

Cisco 4000 Series Integrated Services Routers Overview

The Cisco 4000 Series ISRs are modular routers with LAN and WAN connections that can be configured by means of interface modules, including Cisco Enhanced Service Modules (SM-Xs), and Network Interface Modules (NIMs).

The following table lists the router models that belong to the Cisco 4000 Series ISRs.

Cisco 4400 Series ISR	Cisco 4300 Series ISR	Cisco 4200 Series ISR
Cisco 4431 ISR	Cisco 4321 ISR	Cisco 4221 ISR
Cisco 4451-X ISR	Cisco 4331 ISR	
Cisco 4461 ISR	Cisco 4351 ISR	

System Requirements

The following are the minimum system requirements:



Note There is no change in the system requirements from the earlier releases.

- Memory: 4 GB DDR3 up to 32 GB
- Hard Drive: 200 GB or higher (Optional). The hard drive is only required for running services such as Cisco ISR-WAAS.
- Flash Storage: 4 GB to 32 GB
- NIMs and SM-Xs: Modules (Optional)
- NIM SSD (Optional)

For more information, see the [Cisco 4000 Series ISRs Data Sheet](#).



Note For more information on the Cisco WAAS IOS-XE interoperability, see the WAAS Release Notes: <https://www.cisco.com/c/en/us/support/routers/wide-area-application-services-waas-software/products-release-notes-list.html>.

Determining the Software Version

You can use the following commands to verify your software version:

- For a consolidated package, use the **show version** command
- For individual sub-packages, use the **show version installed** command

Upgrading to a New Software Release

To install or upgrade, obtain a Cisco IOS XE Gibraltar 16.12.1a consolidated package (image) from Cisco.com. You can find software images at <http://software.cisco.com/download/navigator.html>. To run the router using individual sub-packages, you also must first download the consolidated package and extract the individual sub-packages from a consolidated package.



Note When you upgrade from one Cisco IOS XE release to another, you may see *%Invalid IPv6 address* error in the console log file. To rectify this error, enter global configuration mode, and re-enter the missing IPv6 alias commands and save the configuration. The commands will be persistent on subsequent reloads.

For more information on upgrading the software, see the [How to Install and Upgrade the Software](#) section of the Software Configuration Guide for the Cisco 4000 Series ISRs.

Recommended Firmware Versions

[Table 1: Recommended Firmware Versions, on page 2](#) provides information about the recommended Rommon and CPLD versions for releases prior to Cisco IOS XE Everest 16.4.1.

Table 1: Recommended Firmware Versions

Cisco 4000 Series ISRs	Existing RoMmon	Cisco Field-Programmable Devices
Cisco 4451 ISR	16.7(4r)	15010638 Note Upgrade CLI output has a typo and it would show the version incorrectly as 15010738 instead of 15010638. This does not impact the upgrade.
Cisco 4431 ISR	16.7(4r)	15010638 Note Upgrade CLI output has a typo and it would show the version incorrectly as 15010738 instead of 15010638. This does not impact the upgrade.
Cisco 4351 ISR	16.7(5r)	14101324

Cisco 4000 Series ISRs	Existing RoMmon	Cisco Field-Programmable Devices
Cisco 4331 ISR	16.7(5r)	14101324
Cisco 4321 ISR	16.7(5r)	14101324
Cisco 4221 ISR	16.7(5r)	14101324

Upgrading the ROMMON Version on the Cisco 4000 Series ISR

For information about ROMMON compatibility matrix, and ROMMON upgrading procedure, see the ROMMON Compatibility Matrix and "ROMMON Overview and Basic Procedures" sections in the [Upgrading Field-Programmable Hardware Devices for Cisco 4000 Series ISRs](#).

Upgrading Field-Programmable Hardware Devices

The hardware-programmable firmware is upgraded when Cisco 4000 Series ISR contains an incompatible version of the hardware-programmable firmware. To do this upgrade, a hardware-programmable firmware package is released to customers.

Generally, an upgrade is necessary only when a system message indicates one of the field-programmable devices on the Cisco 4000 Series ISR needs an upgrade, or a Cisco technical support representative suggests an upgrade.

From Cisco IOS XE Release 3.10S onwards, you must upgrade the CPLD firmware to support the incompatible versions of the firmware on the Cisco 4000 Series ISR. For upgrade procedures, see the [Upgrading Field-Programmable Hardware Devices for Cisco 4000 Series ISRs](#).

Feature Navigator

You can use Cisco Feature Navigator to find information about feature, platform, and software image support. To access Cisco Feature Navigator, go to <https://cfngng.cisco.com/>. An account on cisco.com is not required.

Limitations and Restrictions

The following limitations and restrictions apply to all releases:

- [Cisco Unified Threat Defense](#) , on page 3
- [Cisco ISR-WAAS and AppNav-XE Service](#), on page 3
- [USB Etoken](#), on page 4

Cisco Unified Threat Defense

The Cisco Unified Threat Defense (UTD) service requires a minimum of 1 to 4 GB of DRAM.

Cisco ISR-WAAS and AppNav-XE Service

The Cisco ISR-WAAS/AppNav service requires a system to be configured with a minimum of 8GB of DRAM and 16GB flash storage. For large service profiles, 16GB of DRAM and 32GB flash storage is required. Also, Cisco ISR-WAAS requires a minimum of 200GB SSD.

IPsec Traffic

IPsec traffic is restricted on the Cisco 4000 Series ISR. The router has the same IPsec functionality as a Cisco ISR G2. The default behavior of the router will be as follows (unless an HSECK9 license is installed):

- If the limit of 1000 concurrent IPsec tunnels is exceeded, no more tunnels are allowed and the following error message appears:

```
%CERM-4-TUNNEL_LIMIT: Maximum tunnel limit of 1000 reached for Crypto functionality with securityk9 technology package license.
```

- The throughput encrypted traffic supports 250 Mbps.
- The Cisco 4000 Series ISR does not currently support nested SA transformation such as:

```
crypto ipsec transform-set transform-1 ah-sha-hmac esp-3des esp-md5-hmac
crypto ipsec transform-set transform-1 ah-md5-hmac esp-3des esp-md5-hmac
```

- The Cisco 4000 Series ISR does not currently support COMP-LZS configuration.

USB Etoken

USB Etoken is not supported on Cisco IOS XE Denali 16.2.1.

Unified Communication on Cisco 4000 Series ISR

- For T1/E1 clocking design and configuration changes, For detailed information, see the following Cisco document: [T1/E1 Voice and WAN Configuration Guide](#).
- For Cisco ISR 4000 Series UC features interpretation with CUCM versions, For detailed information, see the following Cisco document: [Compatibility Matrix](#).
- For High density DSPfarm PVDM (SM-X-PVDM) and PVDM4 DSP planning, For detailed information, see the following Cisco document: [DSP Calculator for DSP planning](#).

Yang Data Models

Effective with Cisco IOS XE Everest 16.5.1b, the Cisco IOS XE YANG models are available in the form of individual feature modules with new module names, namespaces and prefixes. Revision statements embedded in the YANG files indicate if there has been a model revision.

Navigate to <https://github.com/YangModels/yang> > vendor > cisco > xe > 1651, to see the new, main cisco-IOS-XE-native module and individual feature modules attached to this node.

There are also XPATH changes for the access-list in the *Cisco-IOS-XE-acl.yang* schema.

The *README.md* file in the above Github location highlights these and other changes with examples.

New and Changed Information

New Hardware Features in Cisco IOS XE Fuji 16.9.2

The following hardware is introduced in Cisco IOS XE Fuji 16.9.2:

- Cisco 4461 ISR—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/routers/access/4400/hardware/installation/guide4400-4300/C4400_isr.html.

New Software Features in Cisco 4000 Series ISR Release Cisco IOS XE Fuji 16.9.2

There are no new features introduced for Cisco IOS XE Fuji Release 16.9.2.

New Hardware Features in Cisco IOS XE Fuji 16.9.1

No new hardware features were introduced for Cisco 4000 Series ISRs in Cisco IOS XE Fuji 16.9.1.

New Software Features in Cisco 4000 Series ISR Release Cisco IOS XE Fuji 16.9.1

The following features are supported by the Cisco 4000 Series Integrated Services Routers for Cisco IOS XE Fuji 16.9.1:

- For information on migrating from existing Cisco IOS XE 3S releases to the Cisco IOS XE Fuji 16.9.1 release, see [Cisco IOS XE Everest 16.4.1 Migration Guide for Access and Edge Routers](#).
- Supported Technology Configuration Guides—When a technology is supported on Cisco 4000 series ISR, the corresponding technology configuration guide is displayed on the product landing page.
- Address Range command for Object Group—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec_data_zbf/configuration/xe-16-9/sec-data-zbf-xe-16-9-book/sec-zbf-ogacl.html.
- Aanalysis-module Monitoring for NAM/ vNAM—For detailed information, see the following Cisco document:<https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/interface/command/ir-cr-book.html>.
- Application Awareness Capability to ZBFW—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec_data_zbf/configuration/xe-16-9/sec-data-zbf-xe-16-9-book/app-firewall-app-fw.html.
- BNG: Dumping Event-traces—For detailed information, see the following Cisco document:<https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/isg/configuration/xe-16-9/isg-xe-16-9-book/isg-debug-enh.html#GUID-F2F71557-7CA9-405A-B30A-25C660603DB6>.
- Candidate Config Support—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/prog/configuration/169/b_169_programmability_cg/configuring_yang_datamodel.html.
- Cellular Profile Configuration Support on Cisco 4000 Series ISRs—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/routers/access/interfaces/NIM/software/configuration/guide/4GLTENIM_SW.html#35936.
- CME - Support for Cisco IP Conference Phones 7832 and 8832—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/voice_ip_comm/cucme/admin/configuration/manual/cmeadm/cmesoft.html.
- Show Command Improvement: show tech pki —For detailed information, see the following Cisco document:<https://content.cisco.com/chapter.sjs?uri=/searchable/chapter/content/en/us/td/docs/ios-xml/ios/security/s1/sec-s1-cr-book/sec-cr-t1.html.xml>.
- DHCPv4 Client Pptions—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipaddr_dhcp/configuration/xe-16-9/dhcp-xe-16-9-book.html.

- DMVPN Transit Vnet Supported on Azure—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/routers/csr1000/software/azu/b_csr1000config-azure.html.
- Event Trace for PFRv3 Errors and PFRv3 Channels—For detailed information, see the following Cisco document:<https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/pfrv3/configuration/xs-16-9/pfrv3-xe-16-9-book/pfrv3-event-trace.html>
- FlexVPN Enhancements—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec_conn_ike2vpn/configuration/xs-16-9/sec-flex-vpn-xe-16-9-book/sec-cfg-ikev2-flex.html.
- Guest Shell (On-Box Python)—The Guest Shell feature is supported on all Cisco 4000 Series Integrated Services Router platforms including the 4GB RAM SKUs.
- PHY Firmware Update—For detailed information, see the following Cisco document:<https://www.cisco.com/c/en/us/td/docs/routers/access/interfaces/NIM/software/configuration/guide/vdsl2-and-adsl2-nim.html>.
- IKEv2 Event Trace Enhancements—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec_conn_ike2vpn/configuration/xs-16-9/sec-flex-vpn-xe-16-9-book/sec-cfg-ikev2-flex.html.
- IS-IS: Enhancements—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios/iproute_isis/command/reference/irs_book/irs_is2.html .
- IS-IS: Event Trace Improvements—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios/iproute_isis/command/reference/irs_book/irs_is2.html.
- IS-IS: Provide Per-Interface Statistics for CLNS/ISIS Traffic—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios/iproute_isis/command/reference/irs_book/irs_is2.html.
- IPSec VPN with DDNS—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec_conn_vpnav/configuration/xs-16-9/sec-vpn-availability-xe-16-9-book/sec-realtime-ipsec.html.
- IPv6 TACACS on VRF—For detailed information, see the following Cisco document:<https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/security/d1/sec-d1-cr-book.html>.
- L2VPN Pseudowire Redundancies—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/mp_l2_vpns/configuration/xs-16-9/mp-l2-vpns-xe-16-9-book/l2vpn-pseudowire-redundancy.html#GUID-90EA972B-1145-49F1-AE67-C2BF6B4C18AC.
- Monitor Event-trace Crypto PKI Event Command Enhancements—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-en_US/ios-xml/ios/security/m1/sec-m1-cr-book.html
- PMIPv6 Enhancements for Cisco ISRs—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/mob_pmip6/configuration/xs-16-9/mob-pmip6-xe-16-9-book/imo-pmip6-multipath-support.html.
- PKI- Secure Device Provisioning—For detailed information, see the following Cisco document:https://www.cisco.com/en/US/docs/ios-xml/ios/sec_conn_pki/configuration/xs-16-9-1/sec-setup-sdp-piki.html#GUID-2F404010-76F1-42F5-AB84-7BA406475565

- ROMMON Protection On Cisco 4000 Series ISRs—For detailed information, see the following Cisco document: https://www.cisco.com/c/en/us/td/docs/routers/access/4400/software/configuration/xe-16-9/isr4400swcfg-xe-16-9-book/installing_the_software.html#concept_3F15D3B0CBA64CA9BADC3C84FE0C63FB
- Support for Secure SCCP Endpoints and VG on Cisco Unified Survivable Remote Site Telephony—For detailed information, see the following Cisco document: https://www.cisco.com/c/en/us/td/docs/voice_ip_comm/cusrst/admin/sccp_sip_srst/configuration/guide/SCCP_and_SIP_SRST_Admin_Guide/srst_secure_sccp_and_sip.html.
- UC Voice Module Support on Cisco 4461 ISR—For detailed information, see the following Cisco document: https://www.cisco.com/c/en_in/products/collateral/routers/4000-series-integrated-services-routers-isr/datasheet-c78-732542.html
- VXLAN support on IOS-XE—For detailed information, see the following Cisco document: <https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/cether/configuration/xe-16-9/ce-xe-16-9-book/ce-vxlan-support.html>
- vEdge on Cisco 4000 Series ISRs—For detailed information, see the following Cisco document: https://sdwan-docs.cisco.com/Product_Documentation/Getting_Started/Hardware_and_Software_Installation/Software_Installation_and_Upgrade_for_IOS_XE_Routers.
- Wide Area SDG Support on Cisco 4000 Series ISRs—For detailed information, see the following Cisco document:
- Web Root URL Filtering Enhancements—For detailed information, see the following Cisco document: https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec_data_utd/configuration/xe-16-9/sec-data-utd-xe-16-9-book/web-filter.html.
- Web User Interface—Supports an embedded GUI-based device-management tool that provides the ability to provision the router, simplifies device deployment and manageability, and enhances user experience. The following features are supported on Web User Interface from Cisco IOS XE Fuji 16.9.1:
 - Day Zero Configuration
 - Open Shortest Path First (OSPF)
 - For information on how to access the Web User Interface, see Configure the Router for Web User Interface section.
- Candidate Configuration—A temporary configuration that can be modified without changing running configuration. You can then choose when to update the device's configuration with the candidate configuration, by committing and confirming the candidate configuration.
- YANG Data Models—For the list of Cisco IOS XE YANG models available with this release, navigate to <https://github.com/YangModels/yang/tree/master/vendor/cisco/xe/1691>. Revision statements embedded in the YANG files indicate if there has been a model revision. The README.md file in the same github location highlights changes that have been made in the release.

Configure the Cellular Back-off Operation

For a router with 3G/4G interface, sometimes service provider network might be busy, congested, in maintenance or in fault state. In such circumstances, service provider network rejects session activation request from the router by returning reject cause code 33 as a response of the activation request. After the router receives the reject cause, the router uses the back-off operation with the pre-defined timer value which could

be carrier-specific. While back-off operation is in progress, no new session activation request is sent out from the router. After the back-off period is up, new session activation request is sent out from the router.

Note: There is no command to disable the cellular back-off feature on the router.

The following example shows how to configure the cellular back-off feature to stop continuous session activation requests back to the router:

```
Router#show cell 0/2/0 all
Profile 1, Packet Session Status = INACTIVE
Profile 2, Packet Session Status = INACTIVE
Profile 3, Packet Session Status = INACTIVE
.
.
.
Success rate is 0 percent (0/5)
Router#show cell 0/2/0 c
Profile 1, Packet Session Status = INACTIVE
Profile 2, Packet Session Status = INACTIVE
Profile 3, Packet Session Status = INACTIVE
RouterCall end mode = 3GPP
RouterSession disconnect reason type = 3GPP specification defined(6)
RouterSession disconnect reason = Option unsubscribed(33)
RouterEnforcing cellular interface back-off
  Period of back-off = 1 minute(s)
Profile 4, Packet Session Status = INACTIVE
...
Profile 16, Packet Session Status = INACTIVE
.
.
.
Profile 16, Packet Session Status = INACTIVE
```

Configure the Router for Web User Interface

This section explains how to configure the router to access Web User Interface. Web User Interface requires the following basic configuration to connect to the router and manage it.

- An HTTP or HTTPS server must be enabled with local authentication.
- A local user account with privilege level 15 and accompanying password must be configured.
- Vty line with protocol SSH/Telnet must be enabled with local authentication. This is needed for interactive commands.
- For more information on how to configure the router for Web User Interface, see [Cisco 4000 Series ISRs Software Configuration Guide, Cisco IOS XE 17](#).

Entering the Configuration Commands Manually

To enter the Cisco IOS commands manually, complete the following steps:

Before you begin

If you do not want to use the factory default configuration because the router already has a configuration, or for any other reason, you can use the procedure in this section to add each required command to the configuration.

Procedure

- Step 1** Log on to the router through the Console port or through an Ethernet port.
- Step 2** If you use the Console port, and no running configuration is present in the router, the Setup command Facility starts automatically, and displays the following text:
- ```
--- System Configuration Dialog ---

Continue with configuration dialog? [yes/no]:
```
- Enter no so that you can enter Cisco IOS CLI commands directly.
- If the Setup Command Facility does not start automatically, a running configuration is present, and you should go to the next step.
- Step 3** When the router displays the user EXEC mode prompt, enter the **enable** command, and the enable password, if one is configured, as shown in the following example:
- ```
Router> enable
password password
```
- Step 4** Enter config mode by entering the **configure terminal** command, as shown in the following example.
- ```
Router> configure terminal
Router(config)#
```
- Step 5** Using the command syntax shown, create a user account with privilege level 15.
- Step 6** If no router interface is configured with an IP address, configure one so that you can access the router over the network. The following example shows the interface GigabitEthernet 0/0/0 configured.
- ```
Router(config)# interface gigabitethernet 0/0/0
Router(config-if)# ip address 10.10.10.1 255.255.255.248
Router(config-if)# no shutdown
Router(config-if)# exit
```
- Step 7** Configure the router as an http server for nonsecure communication, or as an https server for secure communication. To configure the router as an http server, enter the **ip http server** command shown in the example:
- ```
Router(config)# ip http secure-server
```
- Step 8** Configure the router for local authentication, by entering the **ip http authentication local** command, as shown in the example:
- ```
Router(config)# ip http authentication local
```
- Step 9** Configure the vty lines for privilege level 15. For nonsecure access, enter the transport input telnet command. For secure access, enter the transport input telnet ssh command. An example of these commands follows:
- ```
Router(config)# line vty 0 4
Router(config-line)# privilege level 15
Router(config-line)# login local
Router(config-line)# transport input telnet
Router(config-line)# transport output telnet
Router(config-line)# transport input telnet ssh
Router(config-line)# transport output telnet ssh
Router(config-line)# exit
Router(config)# line vty 5 15
Router(config-line)# privilege level 15
Router(config-line)# login local
```

```
Router(config-line)# transport input telnet
Router(config-line)# transport output telnet
Router(config-line)# transport input telnet ssh
Router(config-line)# transport output telnet ssh
Router(config-line)# end
```

## Resolved and Open Bugs

This section provides information about the bugs in Cisco 4000 Series Integrated Services Routers and describe unexpected behavior. Severity 1 bugs are the most serious bugs. Severity 2 bugs are less serious. Severity 3 bugs are moderate bugs. This section includes severity 1, severity 2, and selected severity 3 bugs.

The open and resolved bugs for this release are accessible through the [Cisco Bug Search Tool](#). This web-based tool provides you with access to the Cisco bug tracking system, which maintains information about bugs and vulnerabilities in this product and other Cisco hardware and software products. Within the [Cisco Bug Search Tool](#), each bug is given a unique identifier (ID) with a pattern of CSCxxNNNNN, where x is any letter (a-z) and N is any number (0-9). The bug IDs are frequently referenced in Cisco documentation, such as Security Advisories, Field Notices and other Cisco support documents. Technical Assistance Center (TAC) engineers or other Cisco staff can also provide you with the ID for a specific bug. The [Cisco Bug Search Tool](#) enables you to filter the bugs so that you only see those in which you are interested.

In addition to being able to search for a specific bug ID, or for all bugs in a product and release, you can filter the open and/or resolved bugs by one or more of the following criteria:

- Last modified date
- Status, such as fixed (resolved) or open
- Severity
- Support cases

You can save searches that you perform frequently. You can also bookmark the URL for a search and email the URL for those search results.




---

**Note** If the bug that you have requested cannot be displayed, this may be due to one or more of the following reasons: the bug ID does not exist, the bug does not have a customer-visible description yet, or the bug has been marked Cisco Confidential.

---

## Using the Cisco Bug Search Tool

For more information about how to use the [Cisco Bug Search Tool](#), including how to set email alerts for bugs and to save bugs and searches, see [Bug Search Tool Help & FAQ](#).

### Before You Begin




---

**Note** You must have a Cisco.com account to log in and access the [Cisco Bug Search Tool](#). If you do not have one, you can register for an account.

---

## Procedure

- Step 1** In your browser, navigate to the [Cisco Bug Search Tool](#) .
- Step 2** If you are redirected to a Log In page, enter your registered Cisco.com username and password and then, click Log In.
- Step 3** To search for a specific bug, enter the bug ID in the Search For field and press Enter.
- Step 4** To search for bugs related to a specific software release, do the following:
- In the Product field, choose Series/Model from the drop-down list and then enter the product name in the text field. If you begin to type the product name, the [Cisco Bug Search Tool](#) provides you with a drop-down list of the top ten matches. If you do not see this product listed, continue typing to narrow the search results.
  - In the Releases field, enter the release for which you want to see bugs.  
The [Cisco Bug Search Tool](#) displays a preview of the results of your search below your search criteria.
- Step 5** To see more content about a specific bug, you can do the following:
- Mouse over a bug in the preview to display a pop-up with more information about that bug.
  - Click on the hyperlinked bug headline to open a page with the detailed bug information.
- Step 6** To restrict the results of a search, choose from one or more of the following filters:

| Filter        | Description                                                                                                                                  |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| Modified Date | A predefined date range, such as last week or last six months.                                                                               |
| Status        | A specific type of bug, such as open or fixed.                                                                                               |
| Severity      | The bug severity level as defined by Cisco. For definitions of the bug severity levels, see <a href="#">Bug Search Tool Help &amp; FAQ</a> . |
| Rating        | The rating assigned to the bug by users of the <a href="#">Cisco Bug Search Tool</a> .                                                       |
| Support Cases | Whether a support case has been opened or not.                                                                                               |

Your search results update when you choose a filter.

## Resolved and Open Bugs in Cisco 4000 Series Integrated Services Routers

### Open Caveats-Cisco IOS XE Fuji 16.9.8

There are no open caveats in this release.

### Resolved Caveats-Cisco IOS XE Fuji 16.9.8

All resolved caveats for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                      |
|----------------------------|--------------------------------------------------------------------------------------------------|
| <a href="#">CSCvt53563</a> | Cisco IOS XE Software NETCONF and RESTCONF Authentication Bypass Vulnerability.                  |
| <a href="#">CSCvw25564</a> | Cisco IOS and IOS XE Software IKEv2 AutoReconnect Feature Denial of Service Vulnerability.       |
| <a href="#">CSCvx41294</a> | High CPU usage caused by \"TCP Timer\" process.                                                  |
| <a href="#">CSCvv12527</a> | Crash in SNMP Engine process while polling chassis ID in LLDP.                                   |
| <a href="#">CSCvv78028</a> | Cisco IOS XE Software Zone-Based Policy Firewall ICMP and UDP Inspection Vulnerability.          |
| <a href="#">CSCvx16081</a> | Cisco IOS XE Software H.323 Application Level Gateway Bypass Vulnerability.                      |
| <a href="#">CSCvx37176</a> | Cisco IOS XE Software Rate Limiting Network Address Translation Denial of Service Vulnerability. |

### Open Caveats-Cisco IOS XE Fuji 16.9.7

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                         |
|----------------------------|-----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvm05934</a> | RSA Keysize > 2048 may cause crash                                                                  |
| <a href="#">CSCvt66541</a> | DNAC Wolverine - Crypto PKI-CRL-IO_1 process crashed in crypto_send_pki_request,crypto_crl_io_proc  |
| <a href="#">CSCvu57706</a> | CUBE fails to send calls with below error after updating IOS to 16.9.5 Error (Resource busy)        |
| <a href="#">CSCvv17488</a> | Cisco 4000 Series ISR + SM-X-ES3-* module-Memory leak in iomd                                       |
| <a href="#">CSCvv36247</a> | Memory Leak in MallocLite / Crypto IKMP                                                             |
| <a href="#">CSCvw51738</a> | Cisco 4000 Series ISR - NIM-ES2 module soft-reload leads to a memory leak in iomd                   |
| <a href="#">CSCvw74609</a> | Cisco 4000 Series ISR LACP Configuration lost: channel-group X "mode active" gets removed on reload |
| <a href="#">CSCvw96723</a> | CP process crashed while I95 driver was adding an IPC response to the receive ring                  |
| <a href="#">CSCvx23482</a> | Cisco 4321 ISR reloading once NIM-1MFT-T1/E1 module is installed.                                   |

### Resolved Caveats-Cisco IOS XE Fuji 16.9.7

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCuv97577</a> | Mishandling of dsmpSession pointer causes a crash                                                    |
| <a href="#">CSCvr50406</a> | Cisco IOS XE IOx GuestShell USB SSD Namespace Protection Privilege Escalation Vulnerability          |
| <a href="#">CSCvr93458</a> | Hub router crashed when run test_mpol_policy_qos_policy_template testcase                            |
| <a href="#">CSCvt70639</a> | Device reload due to tunnel flapping                                                                 |
| <a href="#">CSCvt74346</a> | Router may unexpectedly be reloaded when collecting data from the interface using telemetry/Netconf. |
| <a href="#">CSCvu19733</a> | Evaluation of CVE-2020-11868 for IOS                                                                 |
| <a href="#">CSCvv02486</a> | Random MPLS-TE tunnels with explicit-path stay down after egress interface is bounced.               |
| <a href="#">CSCvv26538</a> | Crash due to a NULL pointer while bringing down PPPoE sessions.                                      |
| <a href="#">CSCvv51048</a> | Memory leak "AAA SESS ATTR"                                                                          |
| <a href="#">CSCvv58056</a> | ACLs may be partially loaded into hardware resulting in unexpected drop or permit                    |
| <a href="#">CSCvv88621</a> | GETVPN: All GM will crash when Primary KS recovers its COOP role after network outage                |
| <a href="#">CSCvw06719</a> | "platform ipsec reassemble transit" tail-drops unencrypted IPv4 Fragments with specific payload      |
| <a href="#">CSCvw11902</a> | Passive FTP doesn't work with NAT                                                                    |
| <a href="#">CSCvw14836</a> | ISR router running 16.9.6 crashes authenticating crypto certificate                                  |
| <a href="#">CSCvw34157</a> | APPNAV CFT Crashes                                                                                   |
| <a href="#">CSCvw48800</a> | unable to transfer 1500 byte IP packet when using BRI bundled Multilink                              |
| <a href="#">CSCvw56517</a> | LMR Unable to hear first seconds of audio                                                            |
| <a href="#">CSCvw57860</a> | Duplicate entries seen in MAC filter table.                                                          |
| <a href="#">CSCvw74609</a> | Cisco 4000 Series ISR LACP Configuration lost: channel-group X "mode active" gets removed on reload  |

## Open Caveats-Cisco IOS XE Fuji 16.9.6

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                        |
|----------------------------|------------------------------------------------------------------------------------|
| <a href="#">CSCvu16200</a> | Router may crash when a SSH session is closed after a TACACS configuration change. |
| <a href="#">CSCvu35559</a> | Memory corruption crash when device is booting up.                                 |

| Caveat ID Number           | Description                                                                                   |
|----------------------------|-----------------------------------------------------------------------------------------------|
| <a href="#">CSCvu57706</a> | CUBE fails to send calls with below error after updating IOS to 16.9.5 Error (Resource busy). |
| <a href="#">CSCvv17488</a> | Cisco 4000 Series ISR with SM-X-ES3 Module- Memory leak in iomd.                              |
| <a href="#">CSCvv21125</a> | Interface qlimit size decreases causing output / tail drops.                                  |
| <a href="#">CSCvv26538</a> | Crash due to a NULL pointer while bringing down PPPoE sessions.                               |

## Resolved Caveats-Cisco IOS XE Fuji 16.9.6

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                            |
|----------------------------|--------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvh24730</a> | PfRv3: Crash while printing the same TCA message.                                                      |
| <a href="#">CSCvi22263</a> | Crashes when IOS is adapting shaping with adaptive QoS over DMVPN configured.                          |
| <a href="#">CSCvi67613</a> | Protocol type for GRE header does not work consistently with "cts sgt inline" enable over auto-tunnel. |
| <a href="#">CSCvm40582</a> | Crashes when entering username with aaa common-criteria policy password.                               |
| <a href="#">CSCvm82184</a> | Memory leak under Key Manager (keyman) process.                                                        |
| <a href="#">CSCvn02456</a> | Router crashes when the calls does not establish after making 2 calls when we set "max-conn 2".        |
| <a href="#">CSCvn33902</a> | CPU spike is seen due to "VTEMPLATE BKG OW Process" when disconnecting PPP users 100 session/sec rate. |
| <a href="#">CSCvp46937</a> | Sync failure and hung calls observed on standby.                                                       |
| <a href="#">CSCvp88044</a> | Performance monitor crashes.                                                                           |
| <a href="#">CSCvq39840</a> | CiscoFlashFile - Get-Next request takes longer time for last file on directory.                        |
| <a href="#">CSCvq43004</a> | Need to check qfp ucode crash with RTCP traffic - chunk memory corruption in RTCP path.                |
| <a href="#">CSCvr10592</a> | After putting caller on hold - caller call leg tx packets are increasing in CUBE.                      |
| <a href="#">CSCvr28935</a> | IOS crash in DHCPd receives unnumbered interfaces.                                                     |
| <a href="#">CSCvr66463</a> | With CRL fetch failed, stuck at failed to send the request. There is another request in progress.      |
| <a href="#">CSCvr75640</a> | LNS crash with Segmentation fault(11) in L2TP mgmt daemon.                                             |
| <a href="#">CSCvr76593</a> | Memory leak in CC-API_VCM and CCSIP_SPI_CONTROL.                                                       |
| <a href="#">CSCvr87906</a> | Cisco 4461 ISR: Large un-fragmented IPSEC packets cause router to crash.                               |

| Caveat ID Number           | Description                                                                                                          |
|----------------------------|----------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvr89957</a> | CFT crashed frequently.                                                                                              |
| <a href="#">CSCvs28073</a> | IOS-XE device has memory leak in linux_iosd-imag.                                                                    |
| <a href="#">CSCvs75958</a> | Cisco 4331 ISR /K9 dialer cannot make calls suddenly.                                                                |
| <a href="#">CSCvs86573</a> | Connect message is never forwarded to the calling side.                                                              |
| <a href="#">CSCvs88686</a> | Cisco 4000 Series ISR crash in cpp_cp_svr due to watchdog timeout.                                                   |
| <a href="#">CSCvt05460</a> | IOS-XE: NAT not work for Active FTP.                                                                                 |
| <a href="#">CSCvt33018</a> | MACsec 128/256 XPN on 40g/100g, stop passing traffic for one of AN and interface link flap seen.                     |
| <a href="#">CSCvt42659</a> | Possible regression Cisco 4000 Series ISR Management port ACL breakage or simply Day One Implementation as designed. |
| <a href="#">CSCvt48480</a> | Flow monitor is removed from interface configuration on reload.                                                      |
| <a href="#">CSCvt54305</a> | Device crashed after Boost license expire.                                                                           |
| <a href="#">CSCvu04426</a> | Cisco 4000 Series reloads with erroneous reload cause code.                                                          |
| <a href="#">CSCvu11115</a> | IOS-XE MTP fails to interwork DTMF RFC2833 from payload 100 to payload 101.                                          |
| <a href="#">CSCvu34009</a> | Calls going through T1 are rejected with "no dsps found" Analog/TDM hairpin calls.                                   |
| <a href="#">CSCvn31903</a> | Cisco 4000 Series CUBE send first register with wrong ip address after reload - SIP-UA.                              |
| <a href="#">CSCvs00961</a> | Memory leak under CCSIP_UDP_SOCKET / MallocLite.                                                                     |
| <a href="#">CSCvs04194</a> | Process = Exec crash seen on dmap longevity testbed with clear cry sa peer several times.                            |
| <a href="#">CSCvs08368</a> | FlexVPN Hub Memory Leak in AAA process when IKEv2 sessions are being established                                     |
| <a href="#">CSCvs12349</a> | NeMo tunnel is down after cellular interface config is overwritten.                                                  |
| <a href="#">CSCvs29412</a> | x509 SSH authentication incorrect UPN value selected.                                                                |
| <a href="#">CSCvs42075</a> | Crash with shared-line command.                                                                                      |
| <a href="#">CSCvs46847</a> | RTP/SRTP interworking fails when 180 and 183 have different to-tag.                                                  |
| <a href="#">CSCvs55066</a> | Cisco 4000 Series ISR: MGCP status remains down and does not register with CUCM after a reboot or power cycle.       |
| <a href="#">CSCvs70206</a> | CUBE DNS cache clear should be limited only to the matched connection id.                                            |
| <a href="#">CSCvs85642</a> | Cisco 4000 Series router crashes when rtp-nte DTMF packet arrives at MTP + BDI.                                      |
| <a href="#">CSCvs92848</a> | Crash due to DHCP relay.                                                                                             |

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvt02534</a> | Cisco 4000 Series ISR- unexpectedly reboots with CENT-BR-0.                                           |
| <a href="#">CSCvt04814</a> | CPP crashes due to a long QoS policy and class name.                                                  |
| <a href="#">CSCvt08178</a> | CUBE crashes when SIP call is forked with active SIP KPML subscription.                               |
| <a href="#">CSCvt10151</a> | Multiple Cisco products Snort HTTP Detection Engine File Policy Bypass vulnerability UTD.             |
| <a href="#">CSCvt21373</a> | Unexpected reload in CPP ucode forced by nat 514 .                                                    |
| <a href="#">CSCvt33226</a> | Cisco 4000 Series ISRS iwth CUBEs - call monitor crashed with Process = AFW_application_process.      |
| <a href="#">CSCvt49705</a> | Device Crash observed with NAT and once there is traffic from outside                                 |
| <a href="#">CSCvt51433</a> | Process sessmgrd crash due to clear radius sg-stats command.                                          |
| <a href="#">CSCvt52825</a> | Memory leak in SCCP TLS Client on unexpected deregister event.                                        |
| <a href="#">CSCvt61876</a> | IOS-XE FW feature crashes while inspecting TCP packet with incorrect session packet state.            |
| <a href="#">CSCvt65588</a> | FlexVPN IKEv2 Tunnel route removed after establishing new IKEv2 SA to another peer.                   |
| <a href="#">CSCvt73592</a> | Missing/corrupt IOS-XE PKSC10 format.                                                                 |
| <a href="#">CSCvt85954</a> | IWAN routers Cisco 4000 Series ISR unexpected reload multiple times.                                  |
| <a href="#">CSCvt89337</a> | Incorrect Source IP when resolving DNS.                                                               |
| <a href="#">CSCvt91720</a> | Router see http wsma request as coming from 192.168.1.5.                                              |
| <a href="#">CSCvt99552</a> | CUBE/LGW: Certificate Unknown Error is observed when cn-san-validate server is configured             |
| <a href="#">CSCvu01690</a> | CPUHOGS produced while executing the command - client fireall access-list.                            |
| <a href="#">CSCvu04665</a> | CUBE keeps sending REINVITES to peer legs leading to high CPU and eventually crashes.                 |
| <a href="#">CSCvu11993</a> | ZBFW drops selfzone generated packets from CPU to host with invalid reason in IOS XE 16.12.x routers. |
| <a href="#">CSCvu14823</a> | Crash on IOS-XE router when authenticating expired IPsec peer certificate.                            |
| <a href="#">CSCvu20470</a> | Memory leak in STUN/MallocLite on ISR G2 CUBE/SIP GW routers leading to memory exhaustion over time.  |
| <a href="#">CSCvu27953</a> | Crash due to a segmentation fault in the "IPsec background proc" process.                             |
| <a href="#">CSCvu40093</a> | Crash when tearing down a PPPoE client session.                                                       |



| Caveat ID Number           | Description                                                                                       |
|----------------------------|---------------------------------------------------------------------------------------------------|
| <a href="#">CSCvu43248</a> | %IP-4-DUPADDR: Duplicate address issue at NAT-HSRP Cisco 4000 Series router.                      |
| <a href="#">CSCvu50302</a> | Survivability.tcl recovery procedure fails on Ingress GW of CCE call flow.                        |
| <a href="#">CSCvu52218</a> | Router crashes frequently on NBAR.                                                                |
| <a href="#">CSCvu87786</a> | CUBE Segmentation Fault at sipSPIFreeOneSCB due to corrupt ccb.                                   |
| <a href="#">CSCvu92620</a> | Secure key agent memory leak in seen only in IOS XE 16.9 release.                                 |
| <a href="#">CSCvv14026</a> | Unexpected reload after running the <b>show voice dsp</b> command while an ISDN Call Disconnects. |

### Open Caveats-Cisco IOS XE Fuji 16.9.5

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvp45666</a> | Kernel crash in netfilter.                                                                            |
| <a href="#">CSCvq39840</a> | CiscoFlashFile - Get-Next request takes longer time for last file on directory.                       |
| <a href="#">CSCvq84990</a> | Remove show ip/ipv6 access-list from syncfd-<ewlc-SIT>17.1-Observed Traceback followed by IOSD crash. |
| <a href="#">CSCvq93850</a> | Passive FTP will fail when going over NAT and either client or server are off a SM-X-ES3.             |
| <a href="#">CSCvr28935</a> | IOS crash in DHCPd Receive with Unnumbered interfaces.                                                |
| <a href="#">CSCvr76593</a> | Memory leak in CC-API_VCM and CCSIP_SPI_CONTROL.                                                      |
| <a href="#">CSCvs00961</a> | Memory leak under CCSIP_UDP_SOCKET / MallocLite.                                                      |
| <a href="#">CSCvs04194</a> | Process = Exec crash seen on dmap longevity testbed with clear cry sa peer several times.             |
| <a href="#">CSCvs10497</a> | cpp_cp_svr fast memory leak when nbar custom protocol is configured.                                  |

### Resolved Caveats-Cisco IOS XE Fuji 16.9.5

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                        |
|----------------------------|----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvj29514</a> | CME: Toll fraud app not automatically trusting traffic from phones.                                |
| <a href="#">CSCvp73666</a> | DNA - LAN Automation does not configure link between Peer Device and PnP Agent due CDP limitation. |
| <a href="#">CSCvq41777</a> | CUBE ha crash of standby unit after call hold from video endpoint.                                 |

| Caveat ID Number           | Description                                                                                     |
|----------------------------|-------------------------------------------------------------------------------------------------|
| <a href="#">CSCVq65366</a> | Cube might crash when sending a SIP message over TLS.                                           |
| <a href="#">CSCVq80928</a> | CME/BE4K SNR: Crash when config changes are made while SNR call is active.                      |
| <a href="#">CSCVr31188</a> | GETVPN gikev2 Secondary KS does not push new policy after merging split condition.              |
| <a href="#">CSCVr33415</a> | Router may crash unexpectedly with Segmentation fault(11), Process = DSMP.                      |
| <a href="#">CSCVr39932</a> | IPSEC install failed IPSEC_PAL_SA shows "unexpected number of parents".                         |
| <a href="#">CSCVr42310</a> | Removing and adding ACL to ASR1K is causing Tracebacks and download to DP failed errors.        |
| <a href="#">CSCVr48349</a> | ESP ucode crashed when running NAT with bpa (CGN).                                              |
| <a href="#">CSCVr51860</a> | Observed Traceback with SRTP-RTP call after hold/resume.                                        |
| <a href="#">CSCVr57565</a> | MGCP Calls with SRTP fail to connect with Cause Value=47 due to T.38 calls.                     |
| <a href="#">CSCVr58230</a> | While signalling forking the CUBE is not Sending Re-INVITE for T.38 with the Authorized header. |
| <a href="#">CSCVr61217</a> | GetVPN-ISR4461// Getvpn traffic is failing with Transport mode with all the versions.           |
| <a href="#">CSCVr66754</a> | CME-ISR4K: BLF working Inconsistently on 16.09.03 [Bad code fix was done in CSCvk49797]         |
| <a href="#">CSCVr76534</a> | Cisco 4000 Seris ISR: Crash seen at process execution.                                          |
| <a href="#">CSCVr90926</a> | CUBE is updating the resolved IP only after the REGISTER expires.                               |
| <a href="#">CSCVr96597</a> | IOS-XE crash after doing a SCEP enrollment.                                                     |
| <a href="#">CSCVr99034</a> | Cisco 4000 Series ISR router crash during updating the OpenDNS bypass whitelist.                |
| <a href="#">CSCVs13960</a> | IWAN High CPU and memory.                                                                       |
| <a href="#">CSCVs29535</a> | IWAN crash related to DCA channel.                                                              |
| <a href="#">CSCVs47682</a> | Router crashed on removing trustpoint on dspfarm profile.                                       |

## Open Caveats - Cisco IOS XE Fuji 16.9.4

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                   |
|----------------------------|-------------------------------------------------------------------------------|
| <a href="#">CSCvh59431</a> | Byte counters for physical interface and subinterface don't match.            |
| <a href="#">CSCvj00317</a> | Memory leak VOIP *MallocLite*                                                 |
| <a href="#">CSCvk39056</a> | Memleak_detect script errors "can't use floating-point value as operand of -" |

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvn02456</a> | Router crashes when the calls doesn't establish after making 2 calls when we set "max-conn 2".       |
| <a href="#">CSCvn46955</a> | Memory leak found in CUBE after the test suite execution.                                            |
| <a href="#">CSCvn76837</a> | DMVPN Phase 2 shortcut triggered from a spoke behind PAT may end up in stuck DNX state.              |
| <a href="#">CSCvn79227</a> | QSIG - SIP - Connected Number Missing leading digit when decoding raw QSIG.                          |
| <a href="#">CSCvn82063</a> | Input CRC counter increasing on Tengi interface.                                                     |
| <a href="#">CSCvo76620</a> | Call drops on CUBE when Hold/Resume switches codec and with midcall-signaling passthru media-change. |
| <a href="#">CSCvp27158</a> | CUE AA leg not cleared on ios after it does blind xfer to sip line.                                  |
| <a href="#">CSCvp31671</a> | Router crashes due to a call loop.                                                                   |
| <a href="#">CSCvp45666</a> | Kernel crash in netfilter.                                                                           |
| <a href="#">CSCvp47723</a> | Cisco 4000 Series ISRs: CME no way audio on calls across E1/PRI, reboot resolves for sometime.       |
| <a href="#">CSCvp65151</a> | CPP Stuck thread when processing IPv6 traffic.                                                       |
| <a href="#">CSCvp69393</a> | Router crashes after snmpget to OID related to NHRP.                                                 |
| <a href="#">CSCvq08226</a> | Cisco 4000 Series ISRs crashes when inserting LTE card.                                              |
| <a href="#">CSCvq14832</a> | CUBE Fails To Take the Accept Header Into Account When Receiving Option Pings.                       |
| <a href="#">CSCvq25297</a> | BRI leased line can't come up automatically after remove/insert one side's cable.                    |
| <a href="#">CSCvq26821</a> | Shaper of the internal crypto interface is incorrectly programmed.                                   |
| <a href="#">CSCvq29575</a> | Voice gateway crash due to segmentation fault in process CCSIP_DNS.                                  |
| <a href="#">CSCvq30306</a> | IOSXE: IOMD / TDL leak seen with tdl_response_xcode_stat_side_t                                      |
| <a href="#">CSCvq31129</a> | AppNav: Optimization failed with Asymmetrical traffic, VRF, FNF and NBAR.                            |
| <a href="#">CSCvq31871</a> | Router crashes with ZBF HA sync.                                                                     |
| <a href="#">CSCvq39787</a> | Support status of Restapi container for CSR has not been documented.                                 |
| <a href="#">CSCvq43004</a> | Need to check qfp ucode crash with RTCP traffic - chunk memory corruption in RTCP path.              |
| <a href="#">CSCvq49000</a> | Supervisor reloaded due to cpp_cp_svr process crashing.                                              |
| <a href="#">CSCvq50202</a> | Class-attributes duplicated after EAP reauthen. in ISG radius proxy scenario.                        |
| <a href="#">CSCvq57205</a> | Recording failures with XMF media forking and SIP preservation timer.                                |

| Caveat ID Number           | Description                                                                                                |
|----------------------------|------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCVq57862</a> | Cable-detect command not reflecting proper status in Analog ports on IOS-XE platforms.                     |
| <a href="#">CSCVq57996</a> | RADIUS attribute 4 (NAS-IP-Address) is not honored.                                                        |
| <a href="#">CSCVq58144</a> | cpp_cp_svr crash in cpp_bqs_rm_yoda_select_sch_exponent                                                    |
| <a href="#">CSCVq58237</a> | Supervisor reload due to cpp_cp_svr crash.                                                                 |
| <a href="#">CSCVq58520</a> | After reload dial-peers with ports that have the 'signal did' command show operational state none.         |
| <a href="#">CSCVq63570</a> | CME SIP: Add custom SK templates support back to 7832/8832 conf phones.                                    |
| <a href="#">CSCVq65366</a> | Cube might crash when sending a SIP message over TLS.                                                      |
| <a href="#">CSCVq67003</a> | CPP microcode core file generated due to HW interrupt.                                                     |
| <a href="#">CSCVq71864</a> | Crash after executing <b>show archive config differences</b> .                                             |
| <a href="#">CSCVq72298</a> | Router crashed on running show policy-map interface <> output command.                                     |
| <a href="#">CSCVq73575</a> | TCP traceroute - response ICMP TTL exceeded packet dropped by ZBFW with NAT enabled.                       |
| <a href="#">CSCVq74418</a> | Connectivity is broken on ingress-replication L2DP/VXLAN.                                                  |
| <a href="#">CSCVq75610</a> | IWAN router crash after upgrading to 16.3.8.                                                               |
| <a href="#">CSCVq78529</a> | Seg Fault 11 crash at cts_ip_sgt_binding_sync on CTS enabled SDA fabric-edge switch stack.                 |
| <a href="#">CSCVq81620</a> | Router crashes with ZBF HA sync.                                                                           |
| <a href="#">CSCVq85329</a> | NEAT/CISP:authenticate SVI interface for Supplicant switch in NEAT port when spanning-tree disabled.       |
| <a href="#">CSCVq85913</a> | FlexVPN with password encryption -- after MasterKey change password in profile is not working.             |
| <a href="#">CSCVq87063</a> | getvpn suiteb:KS sends delete payload to gm's while scheduled rekey after primary KS dead/readed.          |
| <a href="#">CSCVq90343</a> | Secure SIP trunk between SIP-GW/CUBE and CUCM with multiple nodes not coming in to service.                |
| <a href="#">CSCVq90361</a> | NHRP process crash                                                                                         |
| <a href="#">CSCVq91789</a> | When issuing ip helper-addresss x.x.x.x command, <b>show run</b> and <b>show run all</b> show differently. |
| <a href="#">CSCVq92102</a> | VG450: SCCP crashing router while shutdown the process.                                                    |
| <a href="#">CSCVq93197</a> | Hostname is not accepted as a part of "snmp-server host" command.                                          |

| Caveat ID Number           | Description                                                                  |
|----------------------------|------------------------------------------------------------------------------|
| <a href="#">CSCvq93830</a> | IOS XE: RSA Keys randomly getting wiped out after rebooting.                 |
| <a href="#">CSCvq94679</a> | [SDA] Crash due to Segmentation fault(11), Process = ARP Input.              |
| <a href="#">CSCvq95517</a> | Segmentation Fault in IP RIB Update following Virtual-Access Interface flap. |
| <a href="#">CSCvq95756</a> | IPSec SA creation failure causes crash in fman-fp-image.                     |
| <a href="#">CSCvq97906</a> | "DHCPD Receive" process crash.                                               |
| <a href="#">CSCvq98095</a> | Gi0/0/0 interface stays up/up and LED green after cable removed.             |

### Resolved Caveats - Cisco IOS XE Fuji 16.9.4

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                        |
|----------------------------|----------------------------------------------------------------------------------------------------|
| <a href="#">CSCuy75886</a> | Lots of chunk memory leak about SNMP SMALL CHUN and SNMP MEDIUM CHU.                               |
| <a href="#">CSCva76745</a> | Show running-config   format with DHCP pool results in a reload.                                   |
| <a href="#">CSCvc78492</a> | DMVPN : IOS-XE - Unable to pass traffic if spoke to spoke fails to build in phase 2.               |
| <a href="#">CSCvg40933</a> | MoH not heard when conf initiator drops from conference [specifically when Holdee xfers the call]. |
| <a href="#">CSCvg83770</a> | Traceback seen on COOP KS.                                                                         |
| <a href="#">CSCvh11088</a> | Crash on<br>OPF_CSR32_OPF_LOGIC_ERR_LEAF_INT__INT_START_OF_BURST_MARKER_ERR                        |
| <a href="#">CSCvh66339</a> | Linux shell prompt format changed with cEdge image.                                                |
| <a href="#">CSCvh79264</a> | Change the punt cause of packets whose destination is virtual IP from<br>SUBNET_BCAST to FOR_US.   |
| <a href="#">CSCvi60411</a> | SNR call flows hardening with Media Renegotiate Flow.                                              |
| <a href="#">CSCvi86071</a> | Crash seen after configuring SCP path under archive.                                               |
| <a href="#">CSCvj17326</a> | Cisco 4000 Series ISRs crashes in o2_cavm_pci_unlock when forwarding large packets for VPLS.       |
| <a href="#">CSCvj76866</a> | Partial Power Failure in Stack Causes Interfaces to Become <b>shutdown</b>                         |
| <a href="#">CSCvj78876</a> | CUBE: FPI Hung Sessions and Provisioning Failures observed in Standby CUBE.                        |
| <a href="#">CSCvj82585</a> | CCSIP_REGISTER memory leak@__be_voice_reg_bulkreg_initialize                                       |
| <a href="#">CSCvj84601</a> | Called-Station-Id attribute not included in Radius Access-Request.                                 |
| <a href="#">CSCvj90089</a> | Crash while doing a conference call.                                                               |

| Caveat ID Number           | Description                                                                                       |
|----------------------------|---------------------------------------------------------------------------------------------------|
| <a href="#">CSCvk03388</a> | After enabling fac standard, cancel call waiting *1 scenario is not working properly.             |
| <a href="#">CSCvk32783</a> | Standard IPsec support in IOS-XE SDWAN software.                                                  |
| <a href="#">CSCvk42239</a> | Service code when dialed in from sip phone does not toggle ephone 1 status.                       |
| <a href="#">CSCvk58112</a> | Router crash after binding virtual template to IWAN domain.                                       |
| <a href="#">CSCvk74443</a> | Multicast IPv6 ping within VRF return % No valid source address for destination.                  |
| <a href="#">CSCvk75838</a> | Netconf/yang or telemetry retrieval of /trustsec-state/cts-rolebased-policies breaks.             |
| <a href="#">CSCvm06775</a> | ATOM CW is not exchanged after node reload.                                                       |
| <a href="#">CSCvm07861</a> | Process = VTEMPLATE Background Mgr crashed in flexvpn session.                                    |
| <a href="#">CSCvm11235</a> | SRTP to RTP call through IOS-XE CUBE produces static with jitter present.                         |
| <a href="#">CSCvm17348</a> | Callq periodic notification timer needs update after CSCve91511 commit [No functionality impact]  |
| <a href="#">CSCvm19435</a> | Crypto not updated post standby IP address change.                                                |
| <a href="#">CSCvm22142</a> | Critical Authentication affected if Voice VLAN not configured.                                    |
| <a href="#">CSCvm24689</a> | One-way audio to IP phone if phone does hold/resume after 20 minutes on secure SIP GW.            |
| <a href="#">CSCvm39485</a> | Small clock changes or time drifts can cause GETVPN TBAR drops (GDOI/IPSEC-PI).                   |
| <a href="#">CSCvm47675</a> | Stale entry in shared line database on executing no voice register dn.                            |
| <a href="#">CSCvm47690</a> | Addition/Edits to numbered OG ACL using "access-list <>" command does not re-expand the ACL.      |
| <a href="#">CSCvm47984</a> | Cisoc 4331 ISR: XE 16.9.1: snmpwalk error - OID not increasing.                                   |
| <a href="#">CSCvm56135</a> | IOS-XE block CLI "tunnel protection ipsec profile <name> shared" on Virtual-template type tunnel. |
| <a href="#">CSCvm58777</a> | CUBE Gets Stuck In 491 Request Pending When Using TLS.                                            |
| <a href="#">CSCvm77162</a> | FED logs overrun 20,000 times with same trace.                                                    |
| <a href="#">CSCvm80443</a> | IOSd memory leak within DSMIB Server within xqos_malloc_wrapper                                   |
| <a href="#">CSCvm91642</a> | MACsec SAP 128 Bits doesn't work with network-essentials license.                                 |
| <a href="#">CSCvn00104</a> | Software crash due to memory corruption after packet trace was enabled.                           |
| <a href="#">CSCvn03502</a> | SR: CFLOW input intf index is 0xffffffff for Service-engine DSP module interface.                 |
| <a href="#">CSCvn03895</a> | Using MTR in redundant RP systems will reload the standby due to parser return error.             |

| Caveat ID Number           | Description                                                                                         |
|----------------------------|-----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvn08136</a> | Removing FNF config using the command "no vlan config 1-4094" causes watchdog forced crash.         |
| <a href="#">CSCvn15600</a> | RTP-NTE packets in sip-kpml <-> rtp-nte scenario have timestamp 0 on CUBE.                          |
| <a href="#">CSCvn17530</a> | Router Crashes When PKI-CRL-IO_0 Runs out of Stack Space During Failed DNS Lookup for CA Server.    |
| <a href="#">CSCvn23906</a> | DHCP Server sends Renew ACKs to Clients with 00:00:00:00:00:00 MAC in L2 frame.                     |
| <a href="#">CSCvn33127</a> | ISAKMP SA is not deleted even if crypto config is deleted (IPsec NAT-T).                            |
| <a href="#">CSCvn33844</a> | RATE_11M supported cannot be preserved in config after reboot(no lower datarates set as mand.)      |
| <a href="#">CSCvn45732</a> | Device crashing if we unconfigure the NTP on the device.                                            |
| <a href="#">CSCvn47985</a> | ACL remarks not handled correctly by Cisco-IOS-XE-acl YANG model.                                   |
| <a href="#">CSCvn51557</a> | Negating dialer watch-list command without alternating the entered CLI command.                     |
| <a href="#">CSCvn57892</a> | High Memory utilization due to Wireless Manager IOSD process.                                       |
| <a href="#">CSCvn61039</a> | Cisco 4000 Series ISRs - 'control-plane host' feature was moved to APPX feature set.                |
| <a href="#">CSCvn69629</a> | ND packets received in remote vtep SISF table - EVPN part.                                          |
| <a href="#">CSCvn71373</a> | IOS-XE routers cannot boot due to a bootflash problem.                                              |
| <a href="#">CSCvn76236</a> | Add support for AAA CC <cleartext> secrets.                                                         |
| <a href="#">CSCvn77594</a> | SRTP decryption failure leading to one-way audio issues for hairpin calls on CUBE.                  |
| <a href="#">CSCvn78203</a> | Router crashed when printing logs while constructing rekey packets (GETVPN).                        |
| <a href="#">CSCvn85422</a> | Int index is 0 for the Cellular interface in the exported flow.                                     |
| <a href="#">CSCvn86466</a> | AAA-CC: password type-6/7 should follow the hash design and only work against expiry or be removed. |
| <a href="#">CSCvn92709</a> | SNG_AO unavailable alarms are not clearing after removing the monitor-load feature under policy.    |
| <a href="#">CSCvo00664</a> | SUP reload after running the command " show plat hard qfp act infr bqs debug qmrt_dump "            |
| <a href="#">CSCvo03167</a> | CUBE failed to send BYE on peer leg with 'media stats-disconnect' enabled.                          |
| <a href="#">CSCvo03458</a> | PKI <b>revocation check crl none</b> does not fallback if CRL not reachable.                        |
| <a href="#">CSCvo05000</a> | SIP global binding disappears when the interface to which SIP is bound flaps.                       |
| <a href="#">CSCvo05751</a> | Changes for sending vlan attrs in access request.                                                   |

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvo06817</a> | Router crash while executing show commands using ' ' (pipe) to filter the output.                     |
| <a href="#">CSCvo10145</a> | Memory overlay crash when using include-cui.                                                          |
| <a href="#">CSCvo10491</a> | PnP Agent should detect image upgrade scenario and configure dialer to bring up cellular interface.   |
| <a href="#">CSCvo12745</a> | Packet drop occurs after acl permit configurations.                                                   |
| <a href="#">CSCvo15215</a> | SIP-Notify/KPML to DTMF RTP-NTE interworking fails, NTE packets dont have the marker bit set to TRUE. |
| <a href="#">CSCvo17528</a> | Reload initiated via SNMP on IOS-XE causes a crash                                                    |
| <a href="#">CSCvo19395</a> | Router crashes when removing a crypto map.                                                            |
| <a href="#">CSCvo20620</a> | CUBE DNS SRV Query is not performed for PRACK                                                         |
| <a href="#">CSCvo21122</a> | Memory leak at hman process.                                                                          |
| <a href="#">CSCvo22943</a> | Expected error message is not seen after Configuring MisMatching Bit Length - 16.9 throttle..         |
| <a href="#">CSCvo27553</a> | PKI incorrect fingerprint calculation during CA authentication                                        |
| <a href="#">CSCvo36031</a> | WSMA crash formatting show command output.                                                            |
| <a href="#">CSCvo36948</a> | Router crash when running show aaa user all command.                                                  |
| <a href="#">CSCvo37464</a> | CUBE picks incorrect interface for media after receiving c=IN IP4 0.0.0.0.                            |
| <a href="#">CSCvo38985</a> | Crash at the VRF configuration.                                                                       |
| <a href="#">CSCvo41815</a> | When roaming to another AP, services received from RADIUS are not applied to the session.             |
| <a href="#">CSCvo42105</a> | IOS-XE DHCP server creates option 125 with invalid format.                                            |
| <a href="#">CSCvo43953</a> | Memory leak in CENT-BR-0 process.                                                                     |
| <a href="#">CSCvo45257</a> | mem leak in ios_portal_vty_run_cmd.                                                                   |
| <a href="#">CSCvo46127</a> | MaxSusRate is not working with service class.                                                         |
| <a href="#">CSCvo46138</a> | Stuck CPP Thread while processing H323 packet.                                                        |
| <a href="#">CSCvo47436</a> | IOSXE - firewall corrupts half open list.                                                             |
| <a href="#">CSCvo47824</a> | Cisco 4461 ISR may fail to recognize SFP+ 10GBASE-LR on the latest polaris_dev images.                |
| <a href="#">CSCvo47866</a> | Crash at Process = SCCP Auto Config                                                                   |
| <a href="#">CSCvo57387</a> | Blind Transfer fails due to 491 Request Pending against UPDATE in early dialog                        |



| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvo58098</a> | CTS PACS not downloading to the devices.                                                              |
| <a href="#">CSCvo60302</a> | Deleting one sip-copylist will remove all sip copy-lists from dialpeers.                              |
| <a href="#">CSCvo62584</a> | DHCP discover packets were being dropped at firewall since UDP source port as 0.                      |
| <a href="#">CSCvo67856</a> | In.telnetd process consumes 100% CPU in show process cpu platform sorted.                             |
| <a href="#">CSCvo70504</a> | Missing Calling-Station-ID in Accounting Ticket for Web-Tal locations.                                |
| <a href="#">CSCvo70837</a> | Cisco 4300 ISR: show version IDMGR-3-INVALID_ID: bad id in id_to_ptr traceback.                       |
| <a href="#">CSCvo71381</a> | Dot1x dynamic voice assignment failure after data domain auth such.                                   |
| <a href="#">CSCvo71721</a> | When sending account-logon ISG do not reply with ACK nor NACK.                                        |
| <a href="#">CSCvo73205</a> | Identity policy won't update after config changes.                                                    |
| <a href="#">CSCvo75523</a> | Cisco 4000 Series ISR: Router crash with ZTP using Python script running in guest shell.              |
| <a href="#">CSCvo78685</a> | Ambiguous/unidentical ConnectionID and Fcid during CDR accounting after IOS upgrade.                  |
| <a href="#">CSCvo80960</a> | Streaming CRCs seen with GLC-GE-100FX VID: V02 on ISR4k.                                              |
| <a href="#">CSCvo87827</a> | Crash when polling IPForwarding MIB.                                                                  |
| <a href="#">CSCvo90060</a> | Wrong label programming leading to traffic drop.                                                      |
| <a href="#">CSCvo92514</a> | SDP attribute list corruption causes voice gateway crash.                                             |
| <a href="#">CSCvo99156</a> | Unexpected reload in btrace routines due to division by NULL.                                         |
| <a href="#">CSCvp00579</a> | Bqs may select an inaccurate rate                                                                     |
| <a href="#">CSCvp08738</a> | Router loses <b>transport tcp tls v1.0</b> on reload.                                                 |
| <a href="#">CSCvp10711</a> | Hierarchical QoS stops working on GRE tunnel if dest route flaps between 2nd tunnel and physical int. |
| <a href="#">CSCvp16730</a> | Incoming ESP packets with SPI value starting with 0xFF are dropped due to Invalid SPI error.          |
| <a href="#">CSCvp19568</a> | L2VPN - Xconnect - filtering of LDP targeted hellos using ACL not working.                            |
| <a href="#">CSCvp20770</a> | Nas Identifier not sent in Accounting Packet.                                                         |
| <a href="#">CSCvp26876</a> | PNP profile using hostname is not working anymore.                                                    |
| <a href="#">CSCvp27139</a> | Async lines configuration is not retrievable over netconf                                             |
| <a href="#">CSCvp33578</a> | Crash at the moment of deleting a DVTI.                                                               |

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvp34230</a> | CUBE HA - Global bind is removed during interface flap                                               |
| <a href="#">CSCvp35643</a> | CDP and ping to next hop fails on Ten Gig int after device comes up post "wr er" and reload.         |
| <a href="#">CSCvp39597</a> | Crashes with GRE tunnels configured with QOS over Multilink Frame-relay interfaces.                  |
| <a href="#">CSCvp42709</a> | Cisco 4000 Series ISR NO_PUNT_KEEPALIVE kernel crash due to CP drivers stuck punt and IPC rings.     |
| <a href="#">CSCvp46381</a> | Static nat which has been deleted is shown when <b>show ip nat</b> translation.                      |
| <a href="#">CSCvp47792</a> | VG3x0 - groundstart voice-port configuration removed after reload.                                   |
| <a href="#">CSCvp49863</a> | Incomplete arp in management interface.                                                              |
| <a href="#">CSCvp50733</a> | UTD: Process SSL callback on client hello message as opposed to server response.                     |
| <a href="#">CSCvp60827</a> | Delay of 30 sec while creating a new config file for phone using tftp.                               |
| <a href="#">CSCvp61738</a> | Split DNS not working in case of TCP query coming on WAN interface and destined to LAN interface.    |
| <a href="#">CSCvp63616</a> | Crash due to too many DSPs.                                                                          |
| <a href="#">CSCvp66281</a> | Default ip forward-protocol udp xx changed to no ip forward-protocol udp xx after rollback           |
| <a href="#">CSCvp66443</a> | HTTP Client inside IOS-XE incorrectly reports "Invalid IP address in Hostname" for legal IP address. |
| <a href="#">CSCvp70443</a> | ISDN cause-location command support for switch-type primary-ntt.                                     |
| <a href="#">CSCvp72379</a> | <b>ip dns primary</b> command does not get removed.                                                  |
| <a href="#">CSCvp73344</a> | Standby crash during ISSU.                                                                           |
| <a href="#">CSCvp75121</a> | Ucode crash when PfRv3 and IPv6 monitor are configured on the same tunnel with IPv6 VRF configured.  |
| <a href="#">CSCvp79333</a> | SSH may crash due to a corrupt MAC.                                                                  |
| <a href="#">CSCvp83882</a> | NIM-VAB-A stops forwarding traffic after line resync.                                                |
| <a href="#">CSCvp87195</a> | 200 OK and UPDATE in fast succession causes issue with refresher param in update response.           |
| <a href="#">CSCvp90226</a> | "advertise ospf external" throws application error.                                                  |
| <a href="#">CSCvp91966</a> | When Dial-Peer is Marked Down Due to Option Pings the Call Fails with Cause Value 47.                |
| <a href="#">CSCvp92334</a> | Crash after Media monitor look up.                                                                   |

| Caveat ID Number           | Description                                                                                      |
|----------------------------|--------------------------------------------------------------------------------------------------|
| <a href="#">CSCvp96418</a> | Cisco 4000 Series ISR: BRI ping failure with WIC-1B-S/T-V3 with ISDN 128 leased line.            |
| <a href="#">CSCvp99884</a> | CUBE not passing History-Info header in 181 Call is being forwarded.                             |
| <a href="#">CSCvq00263</a> | Device crashed @ radius_io_stats_timer_handler due to dynamic-author                             |
| <a href="#">CSCvq00619</a> | BGP flap while doing shut/no-shut on a different FPGE interface.                                 |
| <a href="#">CSCvq01055</a> | Replaces string not passed on CUBE REFER consumption scenario when address-hiding is configured. |
| <a href="#">CSCvq04828</a> | VRF aware reverse DNS lookup not working.                                                        |
| <a href="#">CSCvq04989</a> | Ping between 2 Interfaces is not working , dialer interface is interfering in the ARP Process.   |
| <a href="#">CSCvq12723</a> | DPDK: Performing Shut/No-Shut with traffic running can cause packets to silently drop on TX.     |
| <a href="#">CSCvq18105</a> | Cisco 4321 ISR ifOperStatus for Cellular reports Up when it should be dormant.                   |
| <a href="#">CSCvq18328</a> | SSH: host_key->name is not null after reload which prevents SSH from starting up                 |
| <a href="#">CSCvq18793</a> | NIM-2FXS/4FXOP crashing due to DSP failed to reply properly.                                     |
| <a href="#">CSCvq19808</a> | Egress shaping on port-channel sub-intf tail dropping traffic long before rate.                  |
| <a href="#">CSCvq25176</a> | SIP GW/CUBE does not update the change in remote SRTP key on session refresh re-invite.          |
| <a href="#">CSCvq27812</a> | Sessmgr CPU is going high due to DB cursor is not disabled after switchover.                     |
| <a href="#">CSCvq29953</a> | IP SLA react for packetloss and successivepacketloss do not set \$_ipsla_react_type in EEM.      |
| <a href="#">CSCvq36130</a> | Router is on Bootloop after QoS configuration.                                                   |
| <a href="#">CSCvq47186</a> | L2 EVPN: Remote MAC not unfrozen when duplicate cleared with no MAC-only route.                  |
| <a href="#">CSCvq49721</a> | Telnet access fails when VRF-aware extended VTY ACL is configured.                               |
| <a href="#">CSCvq50164</a> | Back out Monolith code of CSCvp10711.                                                            |
| <a href="#">CSCvq58378</a> | Crash after exiting RADIUS server configuration mode.                                            |
| <a href="#">CSCvq59908</a> | Stack crashed after upgrade.                                                                     |
| <a href="#">CSCvq60252</a> | PBR works although an interface is down.                                                         |
| <a href="#">CSCvq76537</a> | CUBE fails to respond to second Session Refresh after refresher is forcefully reversed.          |
| <a href="#">CSCvo15003</a> | CUBE - SDP version increment behaviour creates cypto interworking issues.                        |

| Caveat ID Number           | Description                                            |
|----------------------------|--------------------------------------------------------|
| <a href="#">CSCvq11134</a> | SDP version was incremented due to misplace of PT 100. |

### Open Caveats - Cisco IOS XE Fuji 16.9.3

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                                         |
|----------------------------|---------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvj17588</a> | Cisco 4000 Series ISRs may reload in ""BGP Router" process when interface flap occurs with IPv6 MPLS per vrf routes |
| <a href="#">CSCvn56017</a> | Crash while processing ISIS updates when DiffServ-TE is enabled.                                                    |
| <a href="#">CSCvn78203</a> | Router crashed when printing logs while constructing rekey packets (GETVPN).                                        |
| <a href="#">CSCvo09246</a> | Cisco 4351 ISR communication down few minute after shutdown/no shutdown interface.                                  |
| <a href="#">CSCvo18177</a> | IPV4 routes on the global routing table learnt via BGP refreshes upon adding or removing a VRF.                     |
| <a href="#">CSCvo22398</a> | Cisco 4000 Series ISRs with NIM-ES2 do not forward STP Uplink Fast dummy packet                                     |
| <a href="#">CSCvo24170</a> | Crash due to chunk corruption in ISIS code.                                                                         |
| <a href="#">CSCvo35606</a> | Dialer interface shutdown caused crash of router.                                                                   |
| <a href="#">CSCvo36188</a> | Crash at NAT clear.                                                                                                 |
| <a href="#">CSCvo43897</a> | Cisco4331 ISR , wrongly adding to Port to subscriber field after translation.                                       |
| <a href="#">CSCvo46405</a> | qfp ucode crashed with sRTP traffic - chunk memory corruption.                                                      |
| <a href="#">CSCvo47436</a> | IOS-XE - firewall corrupts half open list.                                                                          |
| <a href="#">CSCvo62122</a> | IOS-XE Router may crash when attempting to Fragment Corrupted IPv4 Packet                                           |
| <a href="#">CSCvo62584</a> | DHCP discover packets were being dropped at firewall since UDP source port as 0.                                    |

### Resolved Caveats - Cisco IOS XE Fuji 16.9.3

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvg29037</a> | Traceback is observed during mid-call media IP and port change.                                       |
| <a href="#">CSCvh77984</a> | Router shows "Flash disk quota exceeded" during the reload, but it still has 60% of free memory left. |
| <a href="#">CSCvj45781</a> | QFP CGM Memory depletion during ISG session churn.                                                    |
| <a href="#">CSCvk20560</a> | 491 not sent in a multiple re-invites in DO2EO scenario.                                              |

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvk62792</a> | IKE Fragmentation payload incorrectly marked as critical.                                             |
| <a href="#">CSCvk73696</a> | MGCP auto-config: Port command under pots dial-peer goes missing from the configuration.              |
| <a href="#">CSCvm01420</a> | CUBE crashes at sipSPI_ipip_vcc_CheckCodecSetType.                                                    |
| <a href="#">CSCvm19399</a> | CRL file is getting overwritten when PKI server turns up after reload.                                |
| <a href="#">CSCvm39894</a> | False authorizations and authentications even without radius server for dot1x/mab.                    |
| <a href="#">CSCvm42441</a> | Router crash when clearing ip nat translations.                                                       |
| <a href="#">CSCvm45068</a> | IOS CUBE Ent does not show 'media anti-trombone' in configuration.                                    |
| <a href="#">CSCvm51112</a> | "clear crypto sa vrf MyVrf" triggers crash after updating pre-shared-keys.                            |
| <a href="#">CSCvm58960</a> | "VoIP dial-Peer <XX> is Busied out" printed in log every 2 minutes when destination is not reachable. |
| <a href="#">CSCvm59483</a> | Host crashes the DSP if ipv6 commands are configured under Service-Engine [Purge ipv6 config option]. |
| <a href="#">CSCvm61279</a> | Crash under AFW_application_process with shared-line configuration.                                   |
| <a href="#">CSCvm62419</a> | Crash at CCB of RTPSPI at the moment of creating a disconnect timer.                                  |
| <a href="#">CSCvm65384</a> | SNMP PKI trap are generated with wrong OID of 6999 instead of 854 per OID assignment.                 |
| <a href="#">CSCvm74894</a> | PKI authentication should proceed even if GetCACaps return any http failure.                          |
| <a href="#">CSCvm76295</a> | [SAP] syncfd fails to start on reload after upgrade to new ES image.                                  |
| <a href="#">CSCvm76452</a> | IPSec background crash while sending SNMP trap.                                                       |
| <a href="#">CSCvm76590</a> | CUBE doesn't forward 200 OK in SRTP-RTP scenario with TCL script on Dial-peer.                        |
| <a href="#">CSCvm83720</a> | Cisoc 4431 ISR GW crashed due to flex_dsprm_vtsp_close.                                               |
| <a href="#">CSCvm86397</a> | CUBE: Crash observed at rbuf_ooh_handler.                                                             |
| <a href="#">CSCvm92019</a> | Media Ant-Trombone does not properly handle a Re-Invite utilizing a Replaces Header.                  |
| <a href="#">CSCvm93603</a> | IP change on dialer-int does not trigger a correct "local cryto entpt" in DMVPN.                      |
| <a href="#">CSCvm94112</a> | DSM-3-INTERNAL: Internal Error : No DSM handle provided traceback on TDM voice gateway.               |
| <a href="#">CSCvm94788</a> | Device reloads when applying #client <IP> vrf Mgmt-vrf server-key 062B0C09586D590B5656390E15.         |
| <a href="#">CSCvm94891</a> | Crash caused by a "TLB Modification exception" after processing a null chunk in "IP Input" process.   |

| Caveat ID Number           | Description                                                                                            |
|----------------------------|--------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvm99036</a> | CUBE Crash in CCSIP_SPI_CONTROL process.                                                               |
| <a href="#">CSCvm99045</a> | IOS-XE PKI: Certificate with 4 dashes imported in trustpool gets lost after reboot.                    |
| <a href="#">CSCvn00218</a> | CUBE Crash in sipSPIAppAddCallInfoUI.                                                                  |
| <a href="#">CSCvn01507</a> | ISR not re-calculating the hash value correctly after payload change.                                  |
| <a href="#">CSCvn01681</a> | IPv6 To/From headers malformed with TCL IVR Script and header-passing.                                 |
| <a href="#">CSCvn02419</a> | Device running IOS-XE 16 Polaris Sees Crash When Performing NAT ALG on FTP Packet.                     |
| <a href="#">CSCvn07614</a> | Out of Band DTMF Events Not Passing to CUCM via SCCP When Using IOS MTP.                               |
| <a href="#">CSCvn14737</a> | Crash with SIP call.                                                                                   |
| <a href="#">CSCvn15588</a> | Loss of two way audio with Skinny Phone, Line instance does not work until the next reboot.            |
| <a href="#">CSCvn15647</a> | ISR4k: "mach vlan" support on Ethernet-internal interface.                                             |
| <a href="#">CSCvn17062</a> | ISR4K: add SCCP MTP single-VRF support with a limitation no traffic from/to other VRF                  |
| <a href="#">CSCvn18500</a> | Certificate map does not work always with UPN in SAN field.                                            |
| <a href="#">CSCvn18790</a> | Cube crash with %SDP-3-SDP_PTR_ERROR.                                                                  |
| <a href="#">CSCvn27579</a> | Cisco 4000 Series ISRs%FMFP-3-OBJ_DWNLD_TO_DP_FAILED:fman_fp_image.                                    |
| <a href="#">CSCvn33961</a> | SSRC-field in RTCP gets changes to 0 when going through TRP present in the media path.                 |
| <a href="#">CSCvn36359</a> | CUBE does not forward INVITE with "midcal-signalling passthru media-change" during a video escalation. |
| <a href="#">CSCvn37915</a> | Crash in cpp_bqs_rm_yoda_proc_pend_fc_cb.                                                              |
| <a href="#">CSCvn41467</a> | Recommit of CSCvm99778 - eca/ewlc/qwlc/mewlc Sanity : AP join failed.                                  |
| <a href="#">CSCvn47534</a> | RTP/SRTP interworking fails when 18x w/o SDP is before 183 w/SDP.                                      |
| <a href="#">CSCvn51553</a> | QFP crashes with a HW interrupt.                                                                       |
| <a href="#">CSCvn53969</a> | Memory leak in SMD process due to AAA Idle-timer not being freed.                                      |
| <a href="#">CSCvn55148</a> | Router not closing TCP connections when "reload" is executed.                                          |
| <a href="#">CSCvn64296</a> | Crash when making an external call.                                                                    |
| <a href="#">CSCvn64397</a> | Incorrect syntax in CRL download URL cause crash.                                                      |
| <a href="#">CSCvn67837</a> | TCP port takes 4 minutes to get released after it is closed.                                           |

| Caveat ID Number           | Description                                                                                       |
|----------------------------|---------------------------------------------------------------------------------------------------|
| <a href="#">CSCvn71041</a> | TACACS group server is not seen, when "transport-map type console test" is configured.            |
| <a href="#">CSCvn78349</a> | FlexVPN with password encryption - keyring aaa LIST password 6 xxxxx encrypted again upon reload. |
| <a href="#">CSCvn78961</a> | Subscribers cannot re-login due to CoA time-out (lite-sessions in routed mode).                   |
| <a href="#">CSCvo00968</a> | Radius attr 32 NAS-IDENTIFIER not sending the FQDN.                                               |
| <a href="#">CSCvo08337</a> | Crash when inserting second NIM-2MFT-T1/E1 in Cisco 4331 ISR.                                     |
| <a href="#">CSCvo15141</a> | CLI "nat force-on" in voice service voip not working as expected.                                 |

### Open Caveats - Cisco IOS XE Fuji 16.9.2

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                                          |
|----------------------------|----------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvj12370</a> | cpp_cp_svr crash in bqs while running QMRT test tool.                                                                |
| <a href="#">CSCvj17588</a> | Cisco 4000 Series ISRs may reload in ""BGP Router" process when interface flap occurs with IPv6 MPLS per vrf routes. |
| <a href="#">CSCvj45781</a> | QFP CGM memory depletion during ISG session churn.                                                                   |
| <a href="#">CSCvk10212</a> | Unable to migrate from ADSL to VDSL without a reboot.                                                                |
| <a href="#">CSCvk59169</a> | Strict SID has NOT been enabled in ISIS segment-routing..                                                            |
| <a href="#">CSCvm59483</a> | Host crashes the DSP if ipv6 commands are configured under Service-Engine [Purge ipv6 config option].                |
| <a href="#">CSCvm61279</a> | Crash under AFW_application_process with shared-line configuration.                                                  |
| <a href="#">CSCvm76590</a> | CUBE does not forward 200 OK in SRTP-RTP scenario with TCL script on Dial-peer.                                      |
| <a href="#">CSCvm78822</a> | The config-sync failure is seen while using 'aaa authorization' commands.                                            |
| <a href="#">CSCvm91323</a> | Router crash with reload reason: LocalSoftADR and core file generated 'cpp-mcplo-ucode'.                             |
| <a href="#">CSCvm94788</a> | Device reloads when applying #client <IP> vrf Mgmt-vrf server-key 062B0C09586D590B5656xxxx.                          |
| <a href="#">CSCvn01507</a> | Cisco 4000 Series ISR is not recalculating the hash value correctly after payload change.                            |
| <a href="#">CSCvn02047</a> | More than 5k NAT entries is causing high CPU utilization even with no traffic.                                       |

### Resolved Caveats - Cisco IOS XE Fuji 16.9.2

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                         |
|----------------------------|-----------------------------------------------------------------------------------------------------|
| <a href="#">CSCuz14861</a> | IOS-XE fails to correctly populate RTCP SSRC field.                                                 |
| <a href="#">CSCve31475</a> | SNMP Error: OID not increasing: @ipAddressIfIndex.ipv6zr                                            |
| <a href="#">CSCvi08303</a> | Standby RP reloads due to config sync failure when Applied Service-insertion WAAS on physical Int.  |
| <a href="#">CSCvi63425</a> | Cisco 4400 ISR router cpp crashed when configured HSRP with PMIPv6.                                 |
| <a href="#">CSCvi92528</a> | ZBFW HA: Configuring redundancy RII on virtual template auto-tunnel does not take effect.           |
| <a href="#">CSCvj16209</a> | CME with external SIP trunk registration results into crash.                                        |
| <a href="#">CSCvj24940</a> | Voice VRF with No Bind OPTIONS ping response not sent.                                              |
| <a href="#">CSCvj25678</a> | The router crashes after failing to modify xcode.                                                   |
| <a href="#">CSCvj27172</a> | The router crashes during Generic Call Filter Module clean-up.                                      |
| <a href="#">CSCvj43156</a> | Crash in XDR process: "fib_rp_table_broker_encode_buf.size <= FIB_RP_TABLE_BROKER_ENC_BUF_SZ".      |
| <a href="#">CSCvj50005</a> | Ciso 4000 Series ISR PPE ucode crashes when processing ipsec traffic on CWS tunnel.                 |
| <a href="#">CSCvj69654</a> | OSPF originates default route without "default-information originate".                              |
| <a href="#">CSCvj73544</a> | OSPF routing loop for external route with multiple VLINKs/ABRs.                                     |
| <a href="#">CSCvj76285</a> | Snmp v2 breaks due to Authentication failure, bad community string, 16.03.06.                       |
| <a href="#">CSCvj78647</a> | MTU CLI is disappeared from show run when interface dialer sh/no shut.                              |
| <a href="#">CSCvj90426</a> | Dash i2c kernel message outputted during boot up.                                                   |
| <a href="#">CSCvj90814</a> | Crash due to memory corruption in Cisco 4000 Series ISR.                                            |
| <a href="#">CSCvj91448</a> | PKI:-IP address parsing issue while printing the subject name if classless IP is used in Trustpoin. |
| <a href="#">CSCvj92862</a> | Netconf returns 255 length byte-stream chars instead of actual length for OSPFV2 Key-string.        |
| <a href="#">CSCvj95351</a> | OSPF SR uloop : After issuing "clear ip ospf process". ospf process crashed.                        |
| <a href="#">CSCvk00446</a> | BGP high CPU when config 256k vxlan static route.                                                   |
| <a href="#">CSCvk02072</a> | Hoot-n-holler multicast traffic marked with DSCP 0.                                                 |
| <a href="#">CSCvk07838</a> | CUBE is using wrong source IP address to send SIP error.                                            |
| <a href="#">CSCvk10633</a> | BGP crashes while running show command and same time bgp peer reset.                                |
| <a href="#">CSCvk10909</a> | ISRV: ONEP process crash during day0 bringup.                                                       |



| Caveat ID Number           | Description                                                                                                         |
|----------------------------|---------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvk12152</a> | Unable to remove command 'ip nat inside destination.'                                                               |
| <a href="#">CSCvk12448</a> | ESP crashes due to fatal error.                                                                                     |
| <a href="#">CSCvk15062</a> | Modification to ZBFW access-lists do not reflect in TCAM.                                                           |
| <a href="#">CSCvk27007</a> | MGCP status remains Down after IOS upgrade caused by CSCvh70570.                                                    |
| <a href="#">CSCvk37875</a> | High Availability system crashes with two Voice Gateways.                                                           |
| <a href="#">CSCvk44570</a> | 16.9 memory leak when create VLAN on ISRs.                                                                          |
| <a href="#">CSCvk53405</a> | Router crash - AFW_application_process.                                                                             |
| <a href="#">CSCvk56331</a> | Initial contact in IKEv1 phase 2 rekey (QM1) causes all crypto sessions to drop.                                    |
| <a href="#">CSCvk56356</a> | NETCONF the IP routes with DHCP are not presented in a consistent way for rpc-reply.                                |
| <a href="#">CSCvk60184</a> | Random crash of data plane with SRTP-SRTP / SRTP-RTP load tests.                                                    |
| <a href="#">CSCvk65072</a> | Crashes due ZBF + NAT.                                                                                              |
| <a href="#">CSCvk65354</a> | Extension Mobility Not working when used with Greek locale on SIP CME.                                              |
| <a href="#">CSCvk66880</a> | CUBE incorrectly fomats SIP SDP.                                                                                    |
| <a href="#">CSCvk69075</a> | No calls shown in output "show call active voice brief" on CUBE and stale entries are present.                      |
| <a href="#">CSCvk69093</a> | CUBE is not responding to SIP INFO.                                                                                 |
| <a href="#">CSCvm02627</a> | Incorrect contact port 5060 used instead of 5061 by CUBE in "302 Moved Temporarily" message.                        |
| <a href="#">CSCvm03744</a> | "%FMFP-3-OBJ_DWNLD_TO_DP_FAILED:fman_fp_image:xxx" appears when configured "ip port-map" on Cisco 4400 Series ISRs. |
| <a href="#">CSCvm06270</a> | ICMP unreachables are not sent to the client on Cisco 1117 ISR platform.                                            |
| <a href="#">CSCvm14346</a> | Cisco ISR/CSR: Memory Corruption of mdl_tbl due to fia-history CLI.                                                 |
| <a href="#">CSCvm16619</a> | CPP-mcplo-ucode crash while encrypting SIP packets with ALG NAT for SIP.                                            |
| <a href="#">CSCvm17883</a> | Standby switch crashes when adding a host name to an object-group.                                                  |
| <a href="#">CSCvm21219</a> | Crash on Running "show vpdn tunnel summary" command.                                                                |
| <a href="#">CSCvm36190</a> | Traceback seen when attempting to recover sw port from bpduguard err-disable state                                  |
| <a href="#">CSCvm51739</a> | SNMP v3 discloses password in the parser warning syslog trap.                                                       |
| <a href="#">CSCvm53491</a> | SIP CME Crashes when Calling Shared Line.                                                                           |
| <a href="#">CSCvm56592</a> | CME/BE4K: Corrupted config file for Auto Registered IP Phones after reload.                                         |

| Caveat ID Number           | Description                                                                                  |
|----------------------------|----------------------------------------------------------------------------------------------|
| <a href="#">CSCvm56670</a> | ACL dropping packets after updating it - %CPPEXMEM-3-NOMEM.                                  |
| <a href="#">CSCvm66103</a> | Crash due to communication failure - IPC (Inter-Procedure Call) messages between DSP and RP. |
| <a href="#">CSCvm67419</a> | Cisco 4400 Series ISRs MACsec drops small frames.                                            |

## Open Caveats - Cisco IOS XE Fuji 16.9.1

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Severity | Description                                                                                       |
|----------------------------|----------|---------------------------------------------------------------------------------------------------|
| <a href="#">CSCuz14861</a> | 2        | IOS-XE Fails to correctly populate RTCP SSRC Field                                                |
| <a href="#">CSCve31475</a> | 2        | SNMP Error: OID not increasing: @ipAddressIfIndex.ipv6z                                           |
| <a href="#">CSCvi08303</a> | 1        | Standby RP Reloads due to Config Sync Failure When Applied Service-insertion WAAS on Physical Int |
| <a href="#">CSCvi63425</a> | 2        | ISR4400 router cpp crashed when configured HSRP with PMIPv6                                       |
| <a href="#">CSCvi92528</a> | 2        | ZBFW HA: Configuring redundancy RII on virtual template auto-tunnel does not take effect          |
| <a href="#">CSCvj16209</a> | 2        | CME with external SIP trunk registration results into crash.                                      |
| <a href="#">CSCvj24940</a> | 2        | Voice VRF with No Bind OPTIONS Ping response not sent                                             |
| <a href="#">CSCvj25678</a> | 2        | Crash after failing to modify xcode                                                               |
| <a href="#">CSCvj27172</a> | 2        | Crash during Generic Call Filter Module cleanup                                                   |
| <a href="#">CSCvj43156</a> | 1        | Crash in XDR process: "fib_rp_table_broker_encode_buf.size <= FIB_RP_TABLE_BROKER_ENC_BUF_SZ"     |
| <a href="#">CSCvj50005</a> | 2        | ISR4K PPE ucode crash when processing ipsec traffic on CWS tunnel                                 |
| <a href="#">CSCvj69654</a> | 2        | OSPF originates default route without "default-information originate"                             |
| <a href="#">CSCvj73544</a> | 2        | ospf routing loop for external route with multiple VLINKs/ABRs                                    |
| <a href="#">CSCvj76285</a> | 2        | Snmp v2 breaks due to Authentication failure, bad community string, 16.03.06                      |
| <a href="#">CSCvj78647</a> | 2        | mtu cli is disappeared from show run when interface dialer sh/no shu                              |
| <a href="#">CSCvj90426</a> | 3        | Dash i2c Kernel message outputted during boot up                                                  |
| <a href="#">CSCvj90814</a> | 2        | Crash due to Memory corruption in ISR4k                                                           |

| Caveat ID Number           | Severity | Description                                                                                         |
|----------------------------|----------|-----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvj91448</a> | 2        | PKI:-IP address parsing issue while printing the subject name if classless IP is used in Trustpoint |
| <a href="#">CSCvj92862</a> | 2        | Viptela-netconf returns 255 length byte-stream chars instead of actual length for OSPFV2 Key-string |
| <a href="#">CSCvj95351</a> | 2        | OSPF SR uloop : After issuing "clear ip ospf process". ospf process crashed.                        |
| <a href="#">CSCvk00446</a> | 2        | BGP high CPU when config 256k vxlan static route                                                    |
| <a href="#">CSCvk02072</a> | 2        | Hoot-n-holler multicast traffic marked with DSCP 0                                                  |
| <a href="#">CSCvk07838</a> | 2        | CUBE is using wrong source IP address to send SIP error                                             |
| <a href="#">CSCvk10633</a> | 2        | bgp crash while running show command and same time bgp peer reset                                   |
| <a href="#">CSCvk10909</a> | 1        | ISRV: ONEP process crash during day0 bringup                                                        |
| <a href="#">CSCvk12152</a> | 2        | Unable to remove command 'ip nat inside destination'                                                |
| <a href="#">CSCvk12448</a> | 2        | ESP crash due to fatal error                                                                        |
| <a href="#">CSCvk15062</a> | 2        | Modification to ZBFW access-lists do not reflect in TCAM                                            |
| <a href="#">CSCvk27007</a> | 2        | MGCP status remains Down after IOS upgrade caused by CSCvh70570                                     |
| <a href="#">CSCvk37875</a> | 2        | High Availability system with two Voice Gateways - Crash                                            |
| <a href="#">CSCvk44570</a> | 2        | 16.9 Memory leak when create VLAN on ISRs                                                           |
| <a href="#">CSCvk53405</a> | 1        | Router crash - AFW_application_process                                                              |
| <a href="#">CSCvk56331</a> | 2        | Initial contact in IKEv1 phase 2 rekey (QM1) causes all crypto sessions to drop                     |
| <a href="#">CSCvk56356</a> | 2        | NETCONF the IP routes with DHCP are not presented in a consistent way for rpc-reply                 |
| <a href="#">CSCvk60184</a> | 2        | Random crash of data plane with SRTP-SRTP / SRTP-RTP load tests                                     |
| <a href="#">CSCvk65072</a> | 2        | Crash due ZBF + NAT                                                                                 |
| <a href="#">CSCvk65354</a> | 2        | Extension Mobility Not working when used with Greek locale on SIP CME                               |
| <a href="#">CSCvk66880</a> | 2        | CUBE incorrectly fomats SIP SDP                                                                     |
| <a href="#">CSCvk69075</a> | 2        | No calls shown in output "show call active voice brief" on CUBE & stale entries are present         |
| <a href="#">CSCvk69093</a> | 2        | CUBE is not responding to SIP INFO                                                                  |

| Caveat ID Number           | Severity | Description                                                                                          |
|----------------------------|----------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvm02627</a> | 2        | Incorrect Contact port 5060 used instead of 5061 by CUBE in "302 Moved Temporarily" message          |
| <a href="#">CSCvm03744</a> | 2        | "%FMFP-3-OBJ_DWNLD_TO_DP_FAILED:fman_fp_image:xxx" appears when configured "ip port-map" on ISR44xx. |
| <a href="#">CSCvm06270</a> | 2        | ICMP unreachables are not sent to the client on C1117 platform                                       |
| <a href="#">CSCvm14346</a> | 3        | ISR/CSR - Memory Corruption of mdl_tbl due to fia-history CLI                                        |
| <a href="#">CSCvm16619</a> | 1        | CPP-mcplo-ucode crash while encrypting SIP packets with ALG NAT for SIP                              |
| <a href="#">CSCvm17883</a> | 2        | Standby switch crashes when adding a host name to an object-group                                    |
| <a href="#">CSCvm21219</a> | 1        | Crash on Running "show vpdn tunnel summary" command.                                                 |
| <a href="#">CSCvm36190</a> | 3        | Traceback seen when attempting to recover sw port from bpduguard err-disable state                   |
| <a href="#">CSCvm51739</a> | 1        | SNMP v3 discloses password in the parser warning syslog trap                                         |
| <a href="#">CSCvm53491</a> | 2        | SIP CME Crashes when Calling Shared Line                                                             |
| <a href="#">CSCvm56592</a> | 2        | CME/BE4K: Corrupted config file for Auto Registered IP Phones after reload                           |
| <a href="#">CSCvm56670</a> | 2        | ACL dropping packets after updating it - %CPPEXMEM-3-NOMEM                                           |
| <a href="#">CSCvm66103</a> | 2        | Crash due to communication failure - IPC (Inter-Procedure Call) messages between DSP and RP.         |
| <a href="#">CSCvm67419</a> | 1        | ISR4400 MACsec drops small frames                                                                    |

### Resolved Caveats - Cisco IOS XE Fuji 16.9.1

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                       |
|----------------------------|---------------------------------------------------------------------------------------------------|
| <a href="#">CSCve78802</a> | Cisco 4451 ISR: GLC-TE SFP module cannot up after OIR during traffic                              |
| <a href="#">CSCvf68261</a> | Crash when printing IPSEC anti-replay error.                                                      |
| <a href="#">CSCvf73320</a> | Cisco 4431 ISR crashes while finding NDR with max oif number per multicast grp at scale.          |
| <a href="#">CSCvf76101</a> | First drop error cause Tracebacks observed with IWAN stress.                                      |
| <a href="#">CSCvf76535</a> | B2B NAT HA: Stale NAT translations stuck on primary router after communication loss with standby. |

| Caveat ID Number           | Description                                                                                                  |
|----------------------------|--------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvf84340</a> | IOS crash when logging rx dsp ctrl message out_of_sequence count syslog.                                     |
| <a href="#">CSCvf85386</a> | Incorrect counters in output of "show macsec statistics".                                                    |
| <a href="#">CSCvf86185</a> | NIM-SSD: Inventory of disk0 and disk1 are interchanged on IOS XE 16.x.                                       |
| <a href="#">CSCvf87437</a> | High memory utilization in the QFP of QM RM process.                                                         |
| <a href="#">CSCvf95141</a> | Zone-based Firewall crashes on standby.                                                                      |
| <a href="#">CSCvf98231</a> | Broadcast counters issue on Cisco 4000 Series ISRs.                                                          |
| <a href="#">CSCvg00696</a> | Throughput configuration CLI should log the message "write mem and reload" instead of just relaod.           |
| <a href="#">CSCvg01760</a> | Traceback-CPUHog seen on the device.                                                                         |
| <a href="#">CSCvg03498</a> | The "copy run start all" makes the router stuck.                                                             |
| <a href="#">CSCvg03981</a> | IOS-XE NAT: IP header of tunneled traffic is translated twice (in inner and outer header).                   |
| <a href="#">CSCvg05599</a> | Router does not recalculate UDP checksum after NAT.                                                          |
| <a href="#">CSCvg19203</a> | SBC re-latch does not work as expected in case of ipv4 mask/0.                                               |
| <a href="#">CSCvg21196</a> | Cisco 4000 Series ISRs: SW MTP configured as TRP does not relay PLI/RTCP messages.                           |
| <a href="#">CSCvg26073</a> | QFP Memory leak in cpp_cp_svr with CPP List Hdr chunk.                                                       |
| <a href="#">CSCvg31373</a> | Cisco 4000 Series ISRs : Error Msg (SYS-2-CHUNKEXPANDFAIL: Could not expand chunk pool for ASR1000 SPA TDL). |
| <a href="#">CSCvg31929</a> | Extended the retries on UCSE before NIO control packet loss is detected.                                     |
| <a href="#">CSCvg33403</a> | Incoming call fails with lower layer disconnected call cause=47 error caused by T.38 calls.                  |
| <a href="#">CSCvg33454</a> | Pass load balancing information in IP header to container.                                                   |
| <a href="#">CSCvg39934</a> | SL mode, unthrottled configuration and relaod without saving puts the system in inconsistent state.          |
| <a href="#">CSCvg40430</a> | Cisco 4431 ISR: QFP crashes by a LLC packet received in a serial interface.                                  |
| <a href="#">CSCvg52180</a> | Cisco 4000 Series ISRs: ROMMON upgrade fails on certain IOS-XE 16.x releases.                                |
| <a href="#">CSCvg63492</a> | Cisco 4000 Series ISRs :IOS-XE 16.x: CWS CLI present but the feature is not supported.                       |
| <a href="#">CSCvg65632</a> | CPP 0 failure Stuck Thread resulting in Unexpected Reboot                                                    |
| <a href="#">CSCvg89742</a> | Incorrect pass-through statistics seen during soak run.                                                      |

| Caveat ID Number           | Description                                                                           |
|----------------------------|---------------------------------------------------------------------------------------|
| <a href="#">CSCvg94908</a> | Mgig stack keeps crashing while configuring with Radius commands.                     |
| <a href="#">CSCvi63840</a> | VIG interface counters do not increment with multicast service reflection on IOS-XE.  |
| <a href="#">CSCvj51510</a> | Crash after service-policy APPNAV change on WAAS instance.                            |
| <a href="#">CSCuy30367</a> | ENH: IOS-XE should allow "ip address dhcp" on Tunnel interface.s                      |
| <a href="#">CSCvb69966</a> | Memory leak under LLDP Protocol process.                                              |
| <a href="#">CSCvd62086</a> | ISR4xxx needs to generate puntinject_stats.log.xxxx and save in bootflash.            |
| <a href="#">CSCvf19460</a> | CTS Pac download fails with ISE reachability through loopback interface over vrf      |
| <a href="#">CSCvf37923</a> | Crash due to stack overflow.                                                          |
| <a href="#">CSCvf80363</a> | Rrotate nginx access/error log files                                                  |
| <a href="#">CSCvg16234</a> | ISR receives a control packet (CDP) with a CMD tag it should process it, not drop it. |
| <a href="#">CSCvg51358</a> | DHCPNAK is not sent in roaming scenario.                                              |
| <a href="#">CSCvh02516</a> | Cannot add static route through dynamic NEMO tunnel interface.                        |
| <a href="#">CSCvh16650</a> | Netconf Get routing-state received an errored RPC response.                           |
| <a href="#">CSCvh20041</a> | UDP SLA Probes not working through PMIPv6 tunnel with GETVPN.                         |
| <a href="#">CSCvh26828</a> | Crash in SNMP ENGINE when polling lldpRemChassisId object.                            |
| <a href="#">CSCvh32416</a> | Evaluation of all for CPU Side-Channel Information Disclosure Vulnerability.          |
| <a href="#">CSCvh57050</a> | IGMP multicast SSM-map with DNS does not work with IGMPv3.                            |
| <a href="#">CSCvh60525</a> | CLI aaa common-criteria not available on IPBASEK9 license.                            |
| <a href="#">CSCvh60871</a> | Unexpected Reboot following show platform software adjacency oce [ID].                |
| <a href="#">CSCvh61453</a> | NULL remote_hostname from LAC.                                                        |
| <a href="#">CSCvh62532</a> | System reload when clearing cts pac.                                                  |
| <a href="#">CSCvh63932</a> | Noisy debugs in "periodic" tracelog.                                                  |
| <a href="#">CSCvh68810</a> | 16.8.1:dot1x Clients stops responding ( ping to clinet IP fails) after 2nd SSO.       |
| <a href="#">CSCvh69518</a> | %SYS-3-TIMERNEG:Cannot start timer with negative offset Process= "ARP Background"     |
| <a href="#">CSCvh70297</a> | Redundancy Mode None does not Sync.                                                   |
| <a href="#">CSCvh73134</a> | ISDN memory leak.                                                                     |

| Caveat ID Number           | Description                                                                                                             |
|----------------------------|-------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvh77637</a> | ISDN pri-group cause router get into a loop.                                                                            |
| <a href="#">CSCvh80485</a> | CTS pacs and cts credentials are lost after SSO.                                                                        |
| <a href="#">CSCvh92275</a> | QoS Overrides loadbalancing to per prefix even with only session level policing applied                                 |
| <a href="#">CSCvh97226</a> | Ordering issue for crypto keyring and crypto isakmp profile.                                                            |
| <a href="#">CSCvh99651</a> | AAA-Proxy errors in dmiauthd tracelogs.                                                                                 |
| <a href="#">CSCvi07387</a> | IP dhcp excluded-address deletion issues via netconf.                                                                   |
| <a href="#">CSCvi07402</a> | No increment for input errors in show i/f counters for pkts larger than configured MTU+30 byte.                         |
| <a href="#">CSCvi11665</a> | Virtual-service guest IP accepts broadcast address.                                                                     |
| <a href="#">CSCvi12341</a> | Unable to see device-sensor in accounting message on ISE (MUD URI).                                                     |
| <a href="#">CSCvi20882</a> | Netconf IP-SLA udp-jitter case missing leaf codec.                                                                      |
| <a href="#">CSCvi22603</a> | Flex-LSP tunnel flap on failing active protecting link without WRAP enabled.                                            |
| <a href="#">CSCvi22835</a> | Vz: Non-XE to XE ISSU compatibility issue.                                                                              |
| <a href="#">CSCvi24614</a> | XE 16.8.1: MKA session not coming up consistently after SSO and keepalive timeout.                                      |
| <a href="#">CSCvi25507</a> | Session Mgrd crash observed with XE 16.8.1 image.                                                                       |
| <a href="#">CSCvi31493</a> | Configuration of BGP auto-summary using NETCONF fails.                                                                  |
| <a href="#">CSCvi35143</a> | Repeatedly Tracebacks seen : %INFRA-3-INVALID_GPM_ACCESS: Invalid GPM Load.                                             |
| <a href="#">CSCvi36290</a> | Incorrect BDI configuration state shown by NETCONF on interface creation.                                               |
| <a href="#">CSCvi36351</a> | Standby rp crash on removing member link from port-channel.                                                             |
| <a href="#">CSCvi36875</a> | Restored DB is session-lock locked out with insane timeout after boot                                                   |
| <a href="#">CSCvi60900</a> | DHCP Leasequery Padding contains previously used data.                                                                  |
| <a href="#">CSCvi72769</a> | UDP SLA echo packets not getting encrypted.                                                                             |
| <a href="#">CSCvi89742</a> | Excessive memory (20MB)) allocated for event tracing by lslib subsys.                                                   |
| <a href="#">CSCvj29095</a> | High CPU due to Alignment Corrections - DNS and NBAR.                                                                   |
| <a href="#">CSCvj55797</a> | NETCONF does not list all the ip nat configuration.                                                                     |
| <a href="#">CSCvj56303</a> | NETCONF issue when updating NAT config with VRF keyword.                                                                |
| <a href="#">CSCvj69569</a> | The "show authentication session sw st" broken and session monitoring sessions coming in show auth sess in legacy mode. |

| Caveat ID Number           | Description                                                                          |
|----------------------------|--------------------------------------------------------------------------------------|
| <a href="#">CSCvj79542</a> | Missing interface source template model.                                             |
| <a href="#">CSCvj87392</a> | DHCP server with option 249 pushes only the routes configured in the first instance. |
| <a href="#">CSCvj89345</a> | AVC license should be activated only in case of smart licensing model.               |

## Related Documentation

### Platform-Specific Documentation

For information about the Cisco 4000 Series ISRs and associated services and modules, see:

[Documentation Roadmap for the Cisco 4000 Series ISRs, Cisco IOS XE 16.x](#) .

### Cisco IOS Software Documentation

The Cisco IOS XE Fuji 16.x software documentation set consists of Cisco IOS XE Fuji 16.x configuration guides and Cisco IOS command references. The configuration guides are consolidated platform-independent configuration guides organized and presented by technology. There is one set of configuration guides and command references for the Cisco IOS XE Fuji 16.x release train. These Cisco IOS command references support all Cisco platforms that are running any Cisco IOS XE Fuji 16.x software image.

See [http://www.cisco.com/en/US/products/ps11174/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/ps11174/tsd_products_support_series_home.html)

Information in the configuration guides often includes related content that is shared across software releases and platforms.

Additionally, you can use Cisco Feature Navigator to find information about feature, platform, and software image support. To access Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn> . An account on cisco.com is not required.

### Communications, Services, and Additional Information

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit [Cisco Marketplace](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

### Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.



