



Release Notes for Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms, Cisco IOS XE 17.15.x

First Published: 2024-08-27

Full Cisco Trademarks with Software License

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

About The Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms

The Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms are best-of-breed, 5G-ready, cloud edge platforms designed for accelerated services, multi-layer security, cloud-native agility, and edge intelligence to accelerate your journey to cloud.

Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms with Cisco IOS XE SD-WAN Software deliver Cisco's secure, cloud-scale SD-WAN solution for the branch. The Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms are built for high performance and integrated SD-WAN Services along with flexibility to deliver security and networking services together from the cloud or on premises. It provides higher WAN port density and a redundant power supply capability. The Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms have a wide variety of interface options to choose from—ranging from lower and higher module density with backward compatibility to a variety of existing WAN, LAN, voice, and compute modules. Powered by Cisco IOS XE, fully programmable software architecture, and API support, these platforms can facilitate automation at scale to achieve zero-touch IT capability while migrating workloads to the cloud. The Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms also come with Trustworthy Solutions 2.0 infrastructure that secures the platforms against threats and vulnerabilities with integrity verification and remediation of threats.

The Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms are well suited for medium-sized and large enterprise branch offices for high WAN IPsec performance with integrated SD-WAN services.

For more information on the features and specifications of Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms, refer to the Cisco Catalyst 8300 Series Edge platforms datasheet.



Note Sections in this documentation apply to all models of Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms unless a reference to a specific model is made explicitly.



Note Cisco IOS XE 17.15.1a is the first release for the Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms in the Cisco IOS XE 17.15.x release series.

Product Field Notice

Cisco publishes Field Notices to notify customers and partners about significant issues in Cisco products that typically require an upgrade, workaround or other user action. For more information, see <https://www.cisco.com/c/en/us/support/web/field-notice-overview.html>.

We recommend that you review the field notices to determine whether your software or hardware platforms are affected. You can access the field notices from <https://www.cisco.com/c/en/us/support/web/tsd-products-field-notice-summary.html#%7Etab-product-categories>.

New and Changed Hardware and Software Features

There are no new hardware features in this release.

Feature Navigator

You can use Cisco Feature Navigator (CFN) to find information about the software features, platform, and software image support on Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms. To access Cisco Feature Navigator, go to <https://cfng.cisco.com/>.



Note To access CFN, you do not require an account on cisco.com.

New and Changed Hardware Features

There are no new hardware features in this release.

New and Changed Hardware Features

There are no new hardware features in this release.

New and Changed Software Features in Cisco IOS XE 17.15.1a

Table 1: Software Features in Cisco Catalyst 8200 and Cisco Catalyst 8300 Series Edge Platforms

| Feature | Description |
|---|--|
| Absolute Path for HTTP or HTTPS File Transfer | The File Transfer using HTTP or HTTPS feature allows you to copy files from a remote server to your local device, using the copy command. |
| Cisco Umbrella Scope Credentials | From Cisco IOS XE 17.15.1a, this feature provides the ability to define and configure a new single Cisco Umbrella credential for both Umbrella SIG and Umbrella DNS. |
| Enhanced NAT Management | From Cisco IOS XE 17.15.1a, the Enhanced NAT Management feature enables network operators to safeguard system performance by limiting NAT translations based on CPU usage with the ip nat translation max-entries cpu command. This feature also enables streamlining NAT synchronization in redundant systems using the ip nat settings redundancy optimized-data-sync command. |

| Feature | Description |
|--|--|
| Enhancements to Segment Routing over IPv6 Dataplane | From Cisco IOS XE 17.15.1a, Segment Routing over IPv6 dataplane supports these functionalities: <ul style="list-style-type: none"> • IS-IS Microloop Avoidance • IS-IS Loop-Free Alternate Fast Reroute • IS-IS Topology-Independent Loop-Free Alternate Fast Reroute • OAM Traffic Engineering |
| Flexible Gigabit Ethernet and Fibre Channel Services | Cisco Coarse Wavelength-Division Multiplexing (CWDM) Small Form-Factor Pluggable (SFP) solution allows you to deploy scalable Gigabit Ethernet and Fibre Channel services efficiently. These hot-swappable transceivers convert electrical signals into single-mode fiber-optic interfaces and can be connected to CWDM passive optical systems using standard SC connectors |
| SD-Routing License Management | This release introduces license management support for SD-Routing devices. The supported licensing workflows include license assignment or configuration, license use, and license usage reporting. Depending on the device, these workflows are performed in the Cisco Catalyst SD-WAN Manager or on the device. |
| Configure Multiple WAN Interfaces on Cisco SD-Routing Devices Using a Custom VRF | You can now create a custom VRF that hosts one or more WAN interfaces. You can extend this functionality to create multiple custom VRFs with each VRF hosting multiple WAN interfaces. These WAN interfaces now function as transport interfaces to establish control connections to the Cisco Catalyst SD-WAN Manager. Having multiple WAN interfaces ensures that there is resiliency in control connections and routing of transport traffic. |
| Monitoring SD-Routing Alarms | From Cisco IOS XE 17.15.1a, network administrators can monitor SD-Routing device alarms on Cisco Catalyst SD-WAN Manager. This feature enables SD-Routing devices to record and store various alarms generated by control components and routers. For more information, see Cisco SD-Routing Command Reference Guide . |
| Network-Wide Path Insights on SD-Routing Devices | Network-Wide Path Insights (NWPI) is a tool that allows network administrators to monitor Cisco SD-Routing deployment, identify network and application issues, and optimize the network. |

| Feature | Description |
|---|---|
| Configure DMVPN for SD-Routing Devices | Cisco DMVPN (Dynamic Multipoint VPN) is a routing technique to build a VPN network with multiple sites without having to statically configure all devices. This technique uses tunnelling protocols and encrypted security measures to create virtual connections, or tunnels, between sites. These tunnels are dynamically created as needed, making them both efficient and cost-effective. |
| Enabling Flow Level Flexible NetFlow Support for SD-Routing Devices | The Flow-level Flexible NetFlow (FNF) feature allows you to monitor the NetFlow traffic and view all the flow-level FNF data that is captured including application-level statistics. |
| Seamless Software Upgrade for SD-Routing Devices | This feature explains how to seamlessly upgrade and onboard an existing Cisco Routing device into the Cisco SD-WAN infrastructure. |

ROMMON Compatibility Matrix

The following table lists the ROMMON releases supported in Cisco IOS XE 17.15.x releases.

Table 2: Minimum and Recommended ROMMON Releases Supported on Cisco Catalyst 8200 and Catalyst 8300 Series Edge Platforms

| Platforms | Cisco IOS XE Release | Minimum ROMMON Release Supported for IOS XE | Recommended ROMMON Release Supported for IOS XE |
|--|----------------------|---|---|
| Catalyst 8300 Series Edge Platforms | | | |
| C8300-1N1S-4T2X 6T | 17.15.1a | 17.3(4.2r) | 17.6(6r) |
| C8300-2N2S-4T2X 6T | 17.15.1a | 17.3(4.1r) | 17.7(1r) |
| Catalyst 8200 Series Edge Platforms | | | |
| C8200-1N-4T | 17.15.1a | 17.6(8.1r) | 17.6(8.1r) |
| C8200L-1N-4T | 17.15.1a | 17.6(8.1r) | 17.6(8.1r) |



- Note** For Cisco Catalyst 8200 and 8200L Series Edge platforms, if your ROMMON is at a version lower than 17.6(8.1r), you can upgrade the device to IOS XE 17.15.1a using any of the following methods:
- in bundle mode, manually upgrade the device to Cisco IOS XE 17.12.4. This will auto-upgrade the ROMMON to 17.6(8.1r). You can then upgrade the device to 17.15.1a, OR
 - in bundle mode, manually upgrade the ROMMON to 17.6(8.1r). You can then upgrade the device to 17.15.1a.
 - in install mode, you can upgrade the device to IOS XE 17.15.1a; the ROMMON is auto-upgraded to the recommended version when the device boots.

For Cisco Catalyst 8300 Series Edge platforms, if your ROMMON is at a version lower than the minimum supported version, manually upgrade the device to Cisco IOS XE 17.12.4. This will auto-upgrade the ROMMON to the recommended version. You can then upgrade the device to 17.15.1a.

Upgrade ROMmon

To upgrade the ROMmon version of your device, use these steps:

1. Check the existing version of ROMmon by using **show rom-monitor r0** command. If you are installing Cisco IOS XE software on a new device, skip this step.
2. Review [ROMMON Compatibility Matrix](#) to identify the recommended version of ROMmon software for the device you plan to upgrade.
3. Go to <https://software.cisco.com/#> and download the ROMmon package file.
4. Copy the ROMmon file to flash drive:


```
copy ftp://username:password@IP addressROMmon package file flash:
```
5. Upgrade the ROMmon package using the following command:


```
upgrade rom-monitor filename bootflash:ROMmon package name all
```
6. Execute **reload** command to complete the ROMmon upgrade process
7. Execute **show rom-monitor r0** command to ensure the ROMmon software is upgraded.

Resolved and Open Bugs for Cisco IOS XE 17.15.1a

Resolved Bugs in Cisco IOS XE 17.15.1a

| Identifier | Headline |
|----------------------------|---|
| CSCwj51700 | CPP crashes after re-/configuring ip nat settings pap limit ... bpa feature in high QFP state. |
| CSCwk03686 | Crash due a segmentation fault due a negative value. |
| CSCwk42634 | %PMAN-0-PROCFAILCRIT: R0/0: pvp: A critical process vip_confid_startup_sh has failed (rc 6). |

| Identifier | Headline |
|----------------------------|---|
| CSCwk33173 | EzPM application-performance profile cause memory leak and crash with long-lived idle TCP flows. |
| CSCwk16333 | Device repeatedly crashing in FTMD due to FNF flow add. |
| CSCwj96852 | Return traffic for outside to inside NAT traffic received on one TLOC is forwarded out of other TLOC. |
| CSCwj95633 | SAIE application - no data to display for IOS XE router. |
| CSCwk39131 | Device crashed when issuing show sdwan ftm next-hop chain all . |
| CSCwk37351 | IOS XE router: unexpected reboot during PVDM OIR. |
| CSCwk22225 | FTMD crashes after receiving credentials feature template update. |
| CSCwj48909 | Coredump observed in tracker module while running <code>exp_sig_auto_tunnel</code> suite. |
| CSCwk23723 | Mean queue calculation is incorrect on WRED hierarchical QoS. |
| CSCwk45165 | fman_fp memory leak on device. |
| CSCwj16153 | 10G front-panel port does not go down on single mode fiber when Rx side goes down. |
| CSCwj84949 | Unencrypted traffic due to non-functional IPsec tunnel in FLEXVPN hub & spoke setup. |
| CSCwj90614 | High CPU utilisation for <code>confd_cli</code> . |
| CSCwi81026 | BFD sessions flapping during IPsec rekey in scaled environment. |
| CSCwk39268 | sdn-network-infra-iwan failing to renew with "hash sha256" > 17.11. |
| CSCwj76662 | High memory utilization due to "ftmd" process. |
| CSCwj92560 | STCAPP command removed from device after reload. |
| CSCwk31715 | After deleting a NAT configuration, the IP address still shows up in routing table. |
| CSCwk42253 | Unexpected reboot when a HTTP connection failed with 404 on a controller mode router. |
| CSCwj42448 | APN password in plain text when cellular controller profile is configured. |
| CSCwk12524 | Device reloaded due to ezManage mobile app service. |
| CSCwk44078 | GETVPN / migrating to new KEK RSA key does not trigger GM re-registration. |
| CSCwi99454 | FNF test_tunnel_name_change_CSCvt57024 case failed due to session of pm5 was not alive. |
| CSCwk22942 | Unable to build two IPsec SAs w/same source/destination where one peer is PAT'd through the other. |

| Identifier | Headline |
|----------------------------|---|
| CSCwj96092 | ICMP tracker type (from echo to timestamp) change causes tracker to fail. |
| CSCwj99827 | Device unexpectedly reloads due to a crash in 'vdaemon' process. |
| CSCwj23674 | Dialer interface MAX MTU for PPPOA is 1492. |
| CSCwj02401 | Router reloaded when generating admin tech while processing very high number of flows. |
| CSCwj40223 | appRouteStatisticsTable sequence misordered in CISCO-SDWAN-APP-ROUTE-MIB or OS returns wrong order. |
| CSCwk19725 | add FNF cache limit for show sdwan app-fwd flows. |
| CSCwj86794 | Device crashes while processing an NWPI trace. |
| CSCwj67591 | Chassis activate effective only after second re-try - with new uuid. |
| CSCwj32347 | DIA endpoint tracker not working with ECMP routes. |
| CSCwj41728 | Unable to install the TE agent using http link in CLI |

Open Bugs in Cisco IOS XE 17.15.1a

| Identifier | Headline |
|----------------------------|---|
| CSCwi76516 | esim cellular configuration tamplate deployemt fails. |
| CSCwk75733 | Custom applications may not be programmed properly. |
| CSCwk89256 | Speed mismatch in IOS-XE configuration after device template push. |
| CSCwm07994 | Router crash with stuck threads. |
| CSCwk85704 | match traffic-category add-on CLI push failed. |
| CSCwj01917 | After upgrade, cellular interface IP ADDRESS NEGOTIATED mismatching. |
| CSCwm01269 | Speed test is giving better result from TLOC extension from the secondary router. |
| CSCwj76689 | Device configuration lost after .bin upgrade. |
| CSCwk86355 | File transfer fails: "lost connection". |
| CSCwk49806 | Router rebooted unexpectedly due to process NHRP crash. |
| CSCwk81360 | Router can reboot unexpectedly while configuring NAT static translation. |
| CSCwk62954 | Multiple "match address local interface <int>" not pushed under crypto profile. |
| CSCwk63722 | Startup configuration failure post PKI server enablement. |
| CSCwk97092 | MKA session not coming up after shut/no shut with EVC. |

| Identifier | Headline |
|----------------------------|--|
| CSCwm07564 | data-policy local-tloc-list breaks RTP media stream. |
| CSCwk54544 | ZBFW TCAM misprogramming after rules are reordered. |
| CSCwk74298 | Device denied for template push and some show commands with error application communication failure. |
| CSCwk98578 | GETVPN IPv6 crypto map not shown in interface configuration. |
| CSCwj42448 | APN password in plain text when cellular controller profile is configured. |
| CSCwk70630 | Cannot import device certificate. |
| CSCwk97930 | Crash occurs when IPv6 packets with link-local source are forwarded. |
| CSCwm13223 | Device crashes in IOSd due to malformed DMVPN-5-NHRP_RES_REPLY_IGNORE syslog. |
| CSCwk79454 | Endpoint tracker does not fail if default route is removed. |
| CSCwk90014 | NAT DIA traffic getting dropped due to port allocation failure. |
| CSCwi87546 | Device unexpectedly reboot due to QFP CPP stuck at waiting for rw_lock - lock id of 0 released. |
| CSCwk61238 | RRI static not populating route after reload if stateful IPsec is configured. |
| CSCwm12851 | Device uses 3DES as default rekey algorithm for GETVPN. |
| CSCwk95044 | SPA.smu.bin drops when packet duplication link fails-over. |
| CSCwj87028 | Device showing custom APP as "unknown" for egress traffic when using DRE Opt. |
| CSCwk20995 | PPPoE session with sub-interface getting stuck after reboot. |
| CSCwm08545 | Centralized policy policer worked per PC on the same site not per site/vpn-list. |
| CSCwf62943 | System image file is not set to packages.conf when image expansion fails due to disk space. |
| CSCwm00309 | Packets not hitting the correct data policy after modifying the action of a sequence. |

Related Documentation

- [Hardware Installation Guide for Catalyst 8200 Series Edge Platforms](#)
- [Hardware Installation Guide for Catalyst 8300 Series Edge Platforms](#)
- [Smart Licensing Using Policy for Cisco Enterprise Routing Platforms](#)
- [Cisco Catalyst 8300 and 8200 Series Edge Platforms Software Configuration Guide](#)

Communications, Services, and Additional Information

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit [Cisco DevNet](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.

Documentation Feedback

To provide feedback about Cisco technical documentation, use the feedback form available in the right pane of every online document.

Troubleshooting

For the most up-to-date, detailed troubleshooting information, see the Cisco TAC website at <https://www.cisco.com/en/US/support/index.html>.

Go to **Products by Category** and choose your product from the list, or enter the name of your product. Look under **Troubleshoot and Alerts** to find information for the issue that you are experiencing.