End-of-Sale and End-of-Life Announcement for the Cisco NXOS 6.x

Contents

Overview

Cisco announces the end-of-sale and end-of-life dates for the Cisco NXOS 6.x. The last day to order the affected product(s) is October 1, 2019. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and Dates for the cisco NXOS 6.x

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	September 4, 2019
End-of-Sale Date: OS SW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 1, 2019
Last Ship Date: OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 30, 2019
End of SW Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	January 30, 2021
End of New Service Attachment Date: OS SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 30, 2021
End of Service Contract Renewal Date: OS SW	The last date to extend or renew a service contract for the product.	July 11, 2021
Last Date of Support: OS SW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2022

HW = Hardware   OS SW = Operating System Software   App. SW = Application Software

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M91S2K9-6.2.1	MDS 9100 Supervisor/Fabric-2, NX-OS Software Release	There is currently no replacement product available	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
	6.2(1)	for this product.		
M91S2K9-6.2.3	MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 6.2(3)	There is currently no replacement product available for this product.	-	-
M91S2K9-6.2.5	MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 6.2(5)	There is currently no replacement product available for this product.	-	-
M91S2K9-NPE-6.2.1	MDS 9100 Supervisor/Fabric-2, NX-OS NPE S/W Release 6.2(1)	There is currently no replacement product available for this product.	-	-
M91S3K9-NPE-6.2.1	MDS 9100 Supervisor/Fabric-3, NX-OS NPE S/W 6.2(1)	There is currently no replacement product available for this product.	-	-
M91S3K9-NPE-6.2.13	MDS 9100 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.13	There is currently no replacement product available for this product.	-	-
M91S3K9-NPE-6.2.5	MDS 9100 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(5)	There is currently no replacement product available for this product.	-	-
M91S3K9-NPE-6.2.5A	MDS 9100 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(5a)	There is currently no replacement product available for this product.	-	-
M91S3K9-NPE-6.2.7	MDS 9100 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(7)	There is currently no replacement product available for this product.	-	-
M91S3K9-NPE-6.2.9	MDS 9100 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(9)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M91S3K9-NPE-6.2.9A	MDS 9100 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.9A	There is currently no replacement product available for this product.	-	-
M91S5K9-6.2.11C	MDS 9100 Supervisor/Fabric-5, NX-OS Software Release 6.2.11C	M91S5K9-8.4.1	MDS 9148S NX-OS version 8.4(1)	-
M91S5K9-6.2.13	MDS 9100 Supervisor/Fabric-5, NX-OS Software Release 6.2.13	M91S5K9-8.4.1	MDS 9148S NX-OS version 8.4(1)	-
M91S5K9-6.2.13A	MDS 9100 Supervisor/Fabric-5, NX-OS Software Release 6.2.13A	M91S5K9-8.4.1	MDS 9148S NX-OS version 8.4(1)	-
M91S5K9-6.2.15	MDS 9100 Supervisor/Fabric-5, NX-OS Software Release 6.2.15	M91S5K9-8.4.1	MDS 9148S NX-OS version 8.4(1)	-
M91S5K9-6.2.17	MDS 9100 Supervisor/Fabric-5, NX-OS Software Release 6.2.17	M91S5K9-8.4.1	MDS 9148S NX-OS version 8.4(1)	-
M91S5K9-6.2.19	MDS 9100 Supervisor/Fabric-5, NX-OS Software Release 6.2.19	M91S5K9-8.4.1	MDS 9148S NX-OS version 8.4(1)	-
M91S5K9-6.2.9	MDS 9100 Supervisor/Fabric-5, NX-OS Software Release 6.2.9	M91S5K9-8.4.1	MDS 9148S NX-OS version 8.4(1)	-
M91S5K9-6.2.9A	MDS 9100 Supervisor/Fabric-5, NX-OS Software Release 6.2.9A	M91S5K9-8.4.1	MDS 9148S NX-OS version 8.4(1)	-
M91S5K9-NPE-6.2.13	MDS 9100 Supervisor/Fabric-5, NX-OS NPE SW Release 6.2.13	M91S5K9-NPE-8.4.1	Cisco MDS 9148S 16G FC - NPE Software Image 8.4(1)	-
M91S5K9-NPE-6.2.15	MDS 9100 Supervisor/Fabric-5, NX-OS NPE Software Rel. 6.2.15	M91S5K9-NPE-8.4.1	Cisco MDS 9148S 16G FC - NPE Software Image 8.4(1)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M91S5K9-NPE-6.2.17	MDS 9100 Supervisor/Fabric-5, NX-OS NPE Software Rel. 6.2.17	M91S5K9-NPE-8.4.1	Cisco MDS 9148S 16G FC - NPE Software Image 8.4(1)	-
M91S5K9-NPE-6.2.19	MDS 9100 Supervisor/Fabric-5, NX-OS NPE Software Rel. 6.2.19	M91S5K9-NPE-8.4.1	Cisco MDS 9148S 16G FC - NPE Software Image 8.4(1)	-
M91S5K9-NPE-6.2.9	MDS 9100 Supervisor/Fabric-5, NX-OS NPE SW Release 6.2(9)	M91S5K9-NPE-8.4.1	Cisco MDS 9148S 16G FC - NPE Software Image 8.4(1)	-
M91S5K9-NPE-6.2.9A	MDS 9100 Supervisor/Fabric-5, NX-OS NPE SW Release 6.2.9A	M91S5K9-NPE-8.4.1	Cisco MDS 9148S 16G FC - NPE Software Image 8.4(1)	-
M92S3K9-6.2.1	MDS 9250 Supervisor/Fabric-3, NX-OS Software Release 6.2(1)	M92S3K9-8.3.1	MDS 9200 Supervisor/Fabric-3, NX-OS Software Release 8.3(1)	-
M92S3K9-6.2.21	MDS 9200 Supervisor/Fabric-3, NX-OS Software Release 6.2(21)	M92S3K9-8.3.1	MDS 9200 Supervisor/Fabric-3, NX-OS Software Release 8.3(1)	-
M92S3K9-6.2.3	MDS 9250 Supervisor/Fabric-3, NX-OS Software Release 6.2(3)	M92S3K9-8.3.1	MDS 9200 Supervisor/Fabric-3, NX-OS Software Release 8.3(1)	-
M92S3K9-6.2.5	MDS 9250 Supervisor/Fabric-3, NX-OS Software Release 6.2(5)	M92S3K9-8.3.1	MDS 9200 Supervisor/Fabric-3, NX-OS Software Release 8.3(1)	-
M92S3K9-NPE-6.2.1	MDS 9250 Supervisor/Fabric-3, NX-OS NPE S/W Release 6.2(1)	There is currently no replacement product available for this product.	-	-
M92S3K9-NPE-6.2.5	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(5)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M92S5K9-6.2.11C	MDS 9250i Supervisor/Fabric-3 NX-OS Software Release 6.2.11C	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-6.2.11D	MDS 9250i Supervisor/Fabric-3 NX-OS Software Release 6.2.11D	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-6.2.13	MDS 9250i Supervisor/Fabric-3, NX-OS Software Release 6.2.13	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-6.2.13A	MDS 9250i Supervisor/Fabric-3, NXOS Software Release 6.2.13A	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-6.2.15	MDS 9250i Supervisor/Fabric-3, NX-OS Software Release 6.2.15	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-6.2.17	MDS 9250i Supervisor/Fabric-3, NX-OS Software Release 6.2.17	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-6.2.19	MDS 9250i Supervisor/Fabric-3, NX-OS Software Release 6.2.19	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-6.2.5	MDS 9250i Supervisor/Fabric-3, NX-OS Software Release 6.2(5)	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-6.2.5A	MDS 9250i Supervisor/Fabric-3, NX-OS Software Release 6.2.5a	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-6.2.7	MDS 9250i Supervisor/Fabric-3, NX-OS Software Release 6.2.7	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-6.2.9	MDS 9250i Supervisor/Fabric-3, NX-OS Software Release 6.2.9	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M92S5K9-6.2.9A	MDS 9250i Supervisor/Fabric-3, NX-OS Software Release 6.2.9A	M92S5K9-8.4.1	MDS 9250i NX-OS version 8.4(1)	-
M92S5K9-NPE-6.2.13	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.13	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-NPE-6.2.15	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.15	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-NPE-6.2.17	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.17	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-NPE-6.2.19	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.19	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-NPE-6.2.5	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(5)	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-NPE-6.2.5A	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(5a)	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-NPE-6.2.7	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(7)	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-NPE-6.2.9	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(9)	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-NPE-6.2.9A	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.9A	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-
M92S5K9-NPE-6.211D	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.11D	M92S5K9-NPE-8.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 8.4(1)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M93S3K9-6.2.21	MDS 9300 Supervisor/Fabric-3, NX-OS Software Release 6.2(21)	There is currently no replacement product available for this product.	-	-
M93S5K9-6.2.13	MDS 9300 Supervisor/Fabric, NX-OS Software Release 6.2.13	There is currently no replacement product available for this product.	-	-
M93S5K9-6.2.13A	MDS 9300 Supervisor/Fabric, NX-OS Software Release 6.2.13A	There is currently no replacement product available for this product.	-	-
M93S5K9-6.2.15	MDS 9300 Supervisor/Fabric, NX-OS SW Release 6.2.15	There is currently no replacement product available for this product.	-	-
M93S5K9-6.2.17	MDS 9300 Supervisor/Fabric, NX-OS SW Release 6.2.17	There is currently no replacement product available for this product.	-	-
M93S5K9-6.2.19	MDS 9300 Supervisor/Fabric, NX-OS SW Release 6.2.19	There is currently no replacement product available for this product.	-	-
M93S5K9-NPE-6.2.13	MDS 9300 Supervisor/Fabric, NX-OS NPE SW Release 6.2.13	There is currently no replacement product available for this product.	-	-
M93S5K9-NPE-6.2.15	MDS 9300 Supervisor/Fabric, NX-OS NPE SW Release 6.2.15	There is currently no replacement product available for this product.	-	-
M93S5K9-NPE-6.2.17	MDS 9300 Supervisor/Fabric, NX-OS NPE SW Release 6.2.17	There is currently no replacement product available for this product.	-	-
M93S5K9-NPE-6.2.19	MDS 9300 Supervisor/Fabric, NX-OS NPE SW Release 6.2.19	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.1	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2(1)	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.11C	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2.11C	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.13	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2.13	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.13A	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2.13A	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.15	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2(15)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M95S2K9-6.2.17	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2(17)	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.19	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2(19)	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.3	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2(3)	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.5	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2(5)	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.5A	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.7	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2.7	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.9	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2.9	There is currently no replacement product available for this product.	-	-
M95S2K9-6.2.9A	MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M95S2K9-NPE-6.2.1	MDS 9500 Supervisor/Fabric-2, NX-OS NPE S/W Release 6.2(1)	There is currently no replacement product available for this product.	-	-
M95S2K9-NPE-6.2.13	MDS 9500 Supervisor/Fabric-2, NX-OS NPE SW Release 6.2.13	There is currently no replacement product available for this product.	-	-
M95S2K9-NPE-6.2.15	MDS 9500 Supervisor/Fabric-2, NX-OS NPE SW Release 6.2.15	There is currently no replacement product available for this product.	-	-
M95S2K9-NPE-6.2.17	MDS 9500 Supervisor/Fabric-2, NX-OS NPE SW Release 6.2.17	There is currently no replacement product available for this product.	-	-
M95S2K9-NPE-6.2.19	MDS 9500 Supervisor/Fabric-2, NX-OS NPE SW Release 6.2.17	There is currently no replacement product available for this product.	-	-
M95S2K9-NPE-6.2.5	MDS 9500 Supervisor/Fabric-2, NX-OS NPE SW Release 6.2(5)	There is currently no replacement product available for this product.	-	-
M95S2K9-NPE-6.2.5A	MDS 9500 Supervisor/Fabric-2, NX-OS NPE SW Release 6.2(5a)	There is currently no replacement product available for this product.	-	-
M95S2K9-NPE-6.2.7	MDS 9500 Supervisor/Fabric-2, NX-OS NPE SW Release 6.2(7)	There is currently no replacement product available for this product.	-	-
M95S2K9-NPE-6.2.9	MDS 9500 Supervisor/Fabric-2, NX-OS NPE SW Release 6.2(9)	There is currently no replacement product available for this product.	-	-
M95S2K9-NPE-6.2.9A	MDS 9500 Supervisor/Fabric-2, NX-OS NPE SW Release 6.2.9A	There is currently no replacement product available for this product.	-	-
M97S3K9-6.2.1	MDS 9710 Supervisor/Fabric-3, NX-OS Software Release 6.2(1)	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M97S3K9-6.2.11C	MDS 9700 Supervisor/Fabric-3, NX-OS Software Release 6.2.11C	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.13	MDS 9700 Supervisor/Fabric-3, NX-OS Software Release 6.2.13	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.13A	MDS 9700 Supervisor/Fabric-3, NX-OS Software Release 6.2.13A	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.15	MDS 9700 Supervisor/Fabric-3, NX-OS Software Release 6.2(15)	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.17	MDS 9700 Supervisor/Fabric-3, NX-OS Software Release 6.2(17)	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.19	MDS 9700 Supervisor/Fabric-3, NX-OS Software Release 6.2(19)	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.21	MDS 9700 Supervisor/Fabric-3, NX-OS Software Release 6.2(21)	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.5	MDS 9710 Supervisor/Fabric-3, NX-OS Software Release 6.2(5)	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.5A	MDS 9710 Supervisor/Fabric-3, NX-OS Software Release 6.2(5a)	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.7	MDS 9710 Supervisor/Fabric-3, NX-OS Software Release 6.2(7)	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-6.2.9	MDS 9700 Supervisor/Fabric-3, NX-OS Software Release 6.2(9)	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
M97S3K9-6.2.9A	MDS 9700 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A	M97S3K9-8.4.1	MDS 9700 NX-OS Software Release 8.4(1) for booting on Sup-1	-
M97S3K9-NPE-6.2.1	MDS 9710 Supervisor/Fabric-3, NX-OS NPE S/W Release 6.2(1)	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-
M97S3K9-NPE-6.2.13	MDS 9700 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.13	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-
M97S3K9-NPE-6.2.15	MDS 9700 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(15)	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-
M97S3K9-NPE-6.2.17	MDS 9700 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(17)	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-
M97S3K9-NPE-6.2.19	MDS 9700 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(19)	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-
M97S3K9-NPE-6.2.5	MDS 9710 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(5)	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-
M97S3K9-NPE-6.2.5A	MDS 9710 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(5a)	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-
M97S3K9-NPE-6.2.7	MDS 9710 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(7)	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-
M97S3K9-NPE-6.2.9	MDS 9700 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2(9)	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-
M97S3K9-NPE-6.2.9A	MDS 9700 Supervisor/Fabric-3, NX-OS NPE SW Release 6.2.9A	M97S3K9-NPE-8.4.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 8.4(1)	-

Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco NXOS 6.x through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: https://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of- Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://www.cisco.com/cisco/support/notifications.html.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.