


# Denial of Service (DoS) Vulnerability in Cisco ASA



**Severity:** Medium  
**Cisco-SA-20150629-CVE-2015-4230**  
**CVSS:** 5.0  
**Workarounds:** No Workarounds available  
**Cisco Bug ID:** CSCus91854  
**CVE ID:** [CVE-2015-4230](#)

**Summary:** A Denial of Service (DoS) vulnerability exists in Cisco ASA software versions 9.0(1) through 9.8(2). An attacker can exploit this vulnerability by sending a specially crafted packet to the affected device, causing a denial of service. No workarounds are available.

**Impact:** Denial of Service (DoS). An attacker can cause the affected device to become unresponsive, disrupting network services.

**Exploitability:** This vulnerability is easily exploitable. An attacker can exploit this vulnerability using a specially crafted packet.

**References:** [Cisco Security Advisory: Denial of Service Vulnerability in Cisco ASA](#), [CVE-2015-4230](#), [CSCus91854](#)

**Workarounds:** No workarounds are available for this vulnerability.

**Additional Information:** This vulnerability affects Cisco ASA software versions 9.0(1) through 9.8(2).

**Conclusion:** This is a Denial of Service (DoS) vulnerability in Cisco ASA software versions 9.0(1) through 9.8(2). An attacker can exploit this vulnerability by sending a specially crafted packet to the affected device, causing a denial of service. No workarounds are available.



æœ-ã,çãf%ãfã,ã,ã,ãfãã®è~èç°ãt...ã®1ã«é-çã—ã|æf...ã±é...ãzjã® URL  
ã,çœç•ã—ã€ããç<-ã®è»çè¼%ã,,æ,,è~³ã,'æ-½ã—ãÿã'ã^ã€ã½"ç³¼ãÇç®;ç  
ã"ã®ãf%ã,ãfãf;ãf³ãf^ã®æf...ã±ã-ã€ã,ã,ã,ã,³è£½ã"ã®ã,ãf³ãf%ãf!ãf¼ã,ã,ã,ã³¼è±;ã

## 翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。