

# End-of-Sale and End-of-Life Announcement for the Cisco UCS Intel Xeon Processor E5-4600 v2 Series Spare

### EOL11038

Cisco announces the end-of-sale and end-of-life dates for the Cisco UCS Intel Xeon Processor E5-4600 v2 Series Spare. The last day to order the affected product(s) is December 31, 2017. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco UCS Intel Xeon Processor E5-4600 v2 Series Spare

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	December 19, 2016
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 31, 2017
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 31, 2018
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	December 31, 2018
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 31, 2018
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 31, 2022
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2022

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
UCS-CPU-E5-4603=	2.00 GHz E5-4603 95W 4C/10MB Cache/DDR3 1066MHz/No HS
UCS-CPU-E5-4607=	2.20 GHz E5-4607 95W 6C/12MB Cache/DDR3 1066MHz/No HS
UCS-CPU-E5-4610=	2.40 GHz E5-4610 95W 6C/15MB Cache/DDR3 1333MHz
UCS-CPU-E5-4617=	2.90 GHz E5-4617 130W 6C/15MB Cache/DDR3 1600MHz, No HS

End-of-Sale Product Part Number	Product Description
UCS-CPU-E5-4620=	2.20 GHz E5-4620 95W 8C/16MB Cache/DDR3 1333MHz/No HS
UCS-CPU-E5-4640=	2.40 GHz E5-4640 95W 8C/20MB Cache/DDR3 1600MHz/No HS
UCS-CPU-E5-4650=	2.70 GHz E5-4650 130W 8C/20MB Cache/DDR3 1600MHz/No HS
UCS-CPU-E5-4650L=	2.60 GHz E5-4650L 115W 8C/20MB Cache/DDR3 1600MHz/No HS
UCS-CPU-E54603B=	2.2 GHz E5-4603v2 95W 4C/10M Cache/DDR3 1333MHz/NoHeatSink
UCS-CPU-E54607B=	2.6 GHz E5-4607v2 95W 6C/15M Cache/DDR3 1333MHz/NoHeatSink
UCS-CPU-E54610B=	2.3 GHz E5-4610v2 95W 8C/16M Cache/DDR3 1600MHz/NoHeatSink
UCS-CPU-E54620B=	2.6 GHz E5-4620v2 95W 8C/20M Cache/DDR3 1600MHz/NoHeatSink
UCS-CPU-E54627B=	3.3 GHz E5-4627v2 130W 8C/16M Cache/DDR3 1866MHz/NoHeatSink
UCS-CPU-E54640B=	2.2 GHz E5-4640v2 95W 10C/20M Cache/DDR3 1866MHz/NoHeatSink
UCS-CPU-E54650B=	2.4 GHz E5-4650v2 95W 10C/25M Cache/DDR3 1866MHz/NoHeatSink
UCS-CPU-E54657LB=	2.4 GHz E5-4657Lv2 115W 12C/30MCache/DDR3 1866MHz/NoHeatSink

# **Product Migration Options**

There is no replacement available for the Cisco UCS Intel Xeon Processor E5-4600 v2 Series Spare at this time.

Customers are encouraged to migrate to other Cisco UCS Intel Xeon products. Information about this product can be found at: <a href="http://www.cisco.com/c/en/us/products/servers-unified-computing/ucs-b420-m4-blade-server/index.html">http://www.cisco.com/c/en/us/products/servers-unified-computing/ucs-b420-m4-blade-server/index.html</a>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives\_and\_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco UCS Intel Xeon Processor E5-4600 v2 Series Spare through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <a href="http://www.cisco.com/go/eos">http://www.cisco.com/go/eos</a>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about\_cisco\_takeback\_recycling.html.

## For More Information

For more Information about the other Cisco UCS Intel Xeon products, visit <a href="http://www.cisco.com/c/en/us/products/servers-unified-computing/ucs-b420-m4-blade-server/index.html">http://www.cisco.com/c/en/us/products/servers-unified-computing/ucs-b420-m4-blade-server/index.html</a>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products\_end-of-life\_policy.html. For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod\_warranties\_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <a href="http://www.cisco.com/cisco/support/notifications.html">http://www.cisco.com/cisco/support/notifications.html</a>.

# Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: <a href="http://www.cisco.com/web/feeds/products/end\_of\_life\_rss.xml">http://www.cisco.com/web/feeds/products/end\_of\_life\_rss.xml</a>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

 $Cisco\ has\ more\ than\ 200\ offices\ worldwide.\ Addresses,\ phone\ numbers,\ and\ fax\ numbers\ are\ listed\ on\ the\ Cisco\ Website\ at\ www.cisco.com/go/offices.$ 

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-738350-00 12/16